HISTORY OF DRILLING OPERATIONS

WEST DEASE TEST WELL NO. 1

HUSKY OIL NPR OPERATIONS, INC. Prepared by: Drilling Department Edited by: S. L. Hewitt

For the

U. S. GEOLOGICAL SURVEY Office of the National Petroleum Reserve in Alaska Department of the Interior SEPTEMBER, 1982

TABLE OF CONTENTS

	Page
INTRODUCTION	1
DRILLING SUMMARY	2
GOVERNMENT FORMS AND REPORTS Notice of Intent to Drill	3
Subsequent Notice of Spud Date	4
13-3/8" Casing	5
9-5/8" Casing	6
(Depth Revision)	7 8 11 12
LOCATION DATA As Staked Location Plat	16 17
DRILLING DATA Operations History	18 23 28 29 31
CASING DATA Introduction Casing Tally Summary 13-3/8" Casing Casing Tally 13-3/8" Casing Casing Cement Job 13-3/8" Casing Casing Tally Summary 9-5/8" Casing Casing Tally Summary 9-5/8" Casing Casing Tally 9-5/8" Casing Casing Cement Job 9-5/8" Casing	33 35 36 37 38 39 41
COMPLETION DATA Wellbore Schematic	42 43
APPENDIX NO. 1 - Rig Inventory	1-1
LIST OF FIGURES	
Figure 1, Well Location Map	1

WEST DEASE TEST WELL NO. 1

INTRODUCTION

West Dease Test Well No. 1 is located 26 miles southeast of Barrow, Alaska, on the National Petroleum Reserve (Figure 1). The well is situated 2,295 feet from the east line and 2,464 feet from the north line in protracted Section 21, Township 21 North, Range 14 West, Umiat Meridian (Latitude: $71^{\circ}09'32.65''$ North; Longitude: $155^{\circ}37'45.19''$ West). Alaska State Plane Coordinates are: X = 307,294.09 and Y = 6,276,319.45, Zone 5. Elevations: Ground 5 feet; Pad 7 feet; Kelly Bushing 24 feet. The well was spudded February 19, 1980, and was drilled to a total depth of 4,170 feet. The rig was released on March 26, 1980.

The primary objective was an updip stratigraphic pinchout of the Sag River Sandstone onto the Barrow Arch. The well penetrated into "Argillite" of Pre-Carboniferous age.

Husky Oil NPR Operations, Inc. supervised and directed the drilling and support operations as prime contractor to the Department of the Interior, U. S. Geological Survey, Office of National Petroleum Reserve in Alaska. Brinkerhoff Signal, Inc. was the drilling contractor, and Brinkerhoff Rig 31, a National T-20, was used to drill the well.




FIGURE 1 - WELL LOCATION MAP - WEST DEASE NO. 1

DRILLING SUMMARY

Field operations at the West Dease location began on January 8, 1980, with construction of the drilling pad and camp location. The rig was moved by Rolligon and Cat train from the Walakpa Test Well No. 1 location. The move began February 8, 1980, and was completed and rig-up begun on February 13, 1980.

The 20" conductor was run to 101' and cemented with 175 sacks Permafrost cement. The well was spudded February 19, 1980, at 6:00 a.m., and 17-1/2" hole was drilled to 295'. Seven joints of 13-3/8", 72#, S-95 casing were run, with the shoe at 288'. The casing was cemented with 700 sacks of Permafrost cement at 14.9 ppg, with good returns at 14.5 ppg. The cement was in place February 20, 1980, at 11:45 p.m.

The 13-3/8" blowout preventer equipment was nippled up and 12-1/4" hole drilled to 2945'. The following cores were cut: Core No. 1 from 600' to 630'; Core No. 2 from 1099' to 1129'; Core No. 3 from 1900' to 1930'; Core No. 4 from 2945' to 2975'. Logs were run (DLL/MSFL, BHC-Sonic/GR/TTI, FDC/CNL/GR/CAL, and HDT-Dipmeter) and 16 sidewall cores shot and recovered. The 9-5/8" casing was run (landed shoe at 2970') and cemented with 1,600 sacks of Permafrost cement (slurry weight: 14.8 to 15.0 ppg). The cement was in place March 5, 1980, at 5:30 a.m.

The 9-5/8" blowout preventer equipment was nippled up and the well drilled to 3700' with an 8-1/2" bit. Core No. 5 was cut from 3700' to 3732' and Drill Stem Test No. 1 was run in the interval 3700' to 3730'. No fluid or gas reached the surface during the test, and total recovery was 0.69 barrels of rat hole fluid with less than 1% oil. Maximum bottom hole flowing pressure was 375 psi at 3722'. The initial shut-in pressure was 1,374 psi and final shut-in pressure was 1,602 psi. Cores No. 6 and No. 7 were cut from 3732' to 3850'.

Drilling of 8-1/2" hole continued to 3912'. Cores No. 8 and No. 9 were cut from 3912' to 4033'. Drilling continued to 4150' and Core No. 10 was cut from 4150' to 4160'. The well was drilled to a measured total depth of 4170' and a final log suite run as follows: Temperature Survey, DLL/GR/SP/CAL, FDC/CNL/GR/CAL, BHC-Sonic/GR, MLL/ML/CAL, and HDT-Dipmeter, Velocity Survey, Sidewall Cores (shot 24, recovered 24), and Temperature Survey (second run).

After the final log run, the well was plugged and abandoned. Four plugs were set as follows: Plug No. 1: 175 sacks Permafrost cement, 4038' to 3640'; Plug No. 2: 50 sacks Permafrost cement, 3413' to 3313'; Plug No. 3: 75 sacks Permafrost cement, 3069' to 2859'; Plug No. 4: 50 sacks Permafrost cement, 2816' to 2700'. The mud was reversed to water and the water to diesel above the top of Plug No. 4. This was to allow U. S. Geological Survey personnel to make future temperature measurements. The dry hole marker was installed and the rig was released March 26, 1980, at 6:00 p.m.

Form 9-333 C (May 198)	SUBMIT IN TRIPLICATE* Form approved. Budget Bureau No. 42-R)42 UNITED STATES Other Instructions on reverse side: DEPARTMENT OF THE INTERIOR C. LEASE DESIGNATION AND ARRIAL NO.							
	GEOLOGICAL SURVEY							
NOTIC	E OF INTENT T	ACK	6. IF INDIAN, ALLOTTI	E OR TRIBE NAME				
1s. TIPE OF WORK	TORY							MASS -
b. TIPE OF WELL			N/A					
OIL OAS OFFICE OTHER WILDOW SOME SOME SOME NELL OTHER WALLOW								
2 XINT OF OFFENTON National Petroleum Reserve in Alaska Petroleum Reserve in AF (through Husky Oil NPR Operations, Inc.)								
3. ADDRESS OF CPRATCA								est Well No. 1
2525 C Street,	Suite 400, Anch	OTARE, AK	99 <u>9</u>		ruggi Pem en (s.*)	 i	N/A	OR MITDETA
2295' FEL, 24						į.	11. SEC., T., A., M., DR 4ND SCRYET OR A	BLE.
At proposed prod. see	ie							
Same (straigh	t hole)	281 TOWN CB 705	T OFFICE	••			Sec 21, T21N	
28 miles East-	Southeast of Bar	TOW				1	North Slope	Alaska
15. DISTANCE FROM FROM LOCATION TO NEAREST PROPERTY OF LEARE !) (12 a)		16. NO	OP	ACRES DY LEASE	27. NO. 01	IS MET. L VCSER VERIGNED	
(A)ec to pearest dri	g, pait line, if any) — 63 maga 1961tide	00'	23.	68(000 ED DEFTE	N/A	T OR CABLE TOOLS	
TO MEAREST WELL, D	RILLING, COMPLETED.	,640'	± 2	1000	o '	Rota	rv	
2). ELEVATIONS (Show wh							22 APPROX DATE W	ORE WILL STARTS
Ground = 5'; P	ad = 7'; KB = 24		NG ANI	CE	MENTING PROGRA	M.		
SIEC OF WOLE	SIZE OF CABING	WEIGHT FER P	007		SCTTING DEPTS		OFANTING OF CERT	LPT
26"	20" (Conductor)	133# (K-		*	100 KB	SEE		
17 1/2"	13 3/8" (Deep Conductor)	72# (S-	95)_	-	300 KB	. 	<u>RILLING</u> PROGR	
12 1/4"	9 5/8"	53.5# (S	-95)	±	2850 KB	FOR D	ETAILS	
	ter Program: KB to ± 2850' KB psi, SA Diverter							FIVED DIST. OFFICE
From ± 2850' 12", 3000	KB to TD: psi, SRRA BOP As	sembly					JAN 1	
w/3000 p	si Choke Manifol	d and Kill	Line	2			U.S. 345 95	DIVIDITIRION Cicia di Pyey Peli 444 ka
IX ABOTE SPACE DESCRIPE PROPOSED PROGRAM: If proposal is to deeden or plug back, give data on present productive some and proposed new productive some. If proposal is to drill or deepen directionally, give pertupou data on submurface locations and measured and true vertical depths. Give blowout preventer program, if any 24. ALCHIEF OF Directions DATE January Polytham space for Federal or State office one;								
×0					DATE			
Pany a Bouluse TITLE DISTRICT SUPERVISOR DATE 2-8-80								

*See Instructions On Revene Side

CONTRACT OF THE INTERIOR	5. LEASE
DEPARTMENT OF THE INTERIOR	S/A
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAM.
SUNDRY NOTICES AND REPORTS ON WELLS	7. USST AGREEMENT NAME
reservoir, Use form 9~131–C for such proposals.)	8. FARM OR LEASE NAME National
1. oi) gas other	Petroleum Reserve in Alaska 9. WELL NO.
Z. NAME OF OPERATOR National Petroleum Reserve in	West Dease Fest Well No. 1
Alaska (through Husky 011 NPR Operations, Inc.) 3. ADDRESS OF OPERATOR	N/A N/A
2525 C Street, Suite 400, Anchorage, AX 99503	11. SEC., T., R., M., OR BLK, AND SURVE
 LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17 below.) 	Sec 21, T21N, RI4W, UM
AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same	12. COUNTY OR PARISH 13. STATE: North Slope Alaska
AT TOTAL DEPTH: Same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF - KDB, AND
NOTICE OF INTENT TO: . SUBSEQUENT REPORT OF:	GL 5'; KB 24'
SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Subsequent Report of Spud 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stating and proposed work. If well is	directionally drilled, give subsurface locations
measured and true vertical depths for all markers and zones perting	ent to this work.)*
This well was spudded February 19, 1980, at 6:00 Twenty inch conductor pipe was cemented in place at 101' previous to spudding.	AM. Hole size at spud was 17 l with 175 sacks of Permafrost ce
This well was spudded February 19, 1980, at 6:00 Twenty inch conductor pipe was cemented in place	AM. Hole size at spud was 17 l with 175 sacks of Permafrost ce
This well was spudded February 19, 1980, at 6:00 Twenty inch conductor pipe was cemented in place	with 175 sacks of Permafrost ce
This well was spudded February 19, 1980, at 6:00 Twenty inch conductor pipe was cemented in place	with 175 sacks of Permafrost ce
This well was spudded February 19, 1980, at 6:00 Twenty inch conductor pipe was cemented in place	with 175 sacks of Permafrost ce
This well was spudded February 19, 1980, at 6:00 Twenty inch conductor pipe was cemented in place at 101' previous to spudding.	with 175 sacks of Permafrost ce
This well was spudded February 19, 1980, at 6:00 Twenty inch conductor pipe was cemented in place at 101' previous to spudding. Subsurface Safety Valve: Manu. and Type	with 175 sacks of Permafrost ce
This well was spudded February 19, 1980, at 6:00 Twenty inch conductor pipe was cemented in place at 101' previous to spudding. Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correct	with 175 sacks of Permafrost ce
This well was spudded February 19, 1980, at 6:00 Twenty inch conductor pipe was cemented in place at 101' previous to spudding. Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correct	with 175 sacks of Permafrost ce

"See Instructions on Reverse Side

	UNITED STATES	5. LEASE
	DEPARTMENT OF THE INTERIOR	N/A
	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
		N/A
	SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
	(Do not use this form for proposals to drill or to despen or plug back to a different	N/A
	reservoir, Usa Form 9~331~C for such proposals.)	8. FARM OR LEASE NAME National
	1. oil con gas	Petroleum Reserve in Alaska
	well	9. WELL NO.
-	Z. NAME OF OPERATOR National Petroleum Reserve in	West Dease Test Well No. 1
	Alaska (through Husky Oil NPR Operations, Inc.)	10. FIELD OR WILDCAT NAME
	3. ADDRESS OF OPERATOR	N/A
	2525 C Street, Suite 400, Anchorage, AK 99503	11. SEC., T., R., M., OR BLK. AND SURVEY OR
	4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	AREA
	below.)	Sec 21, T21N, R14W, UM
	AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL! Same	12. COUNTY OR PARISH 13. STATE
	AT TOTAL DEPTH: Same	North Slope Alaska
	Saige	14. API NO.
	16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA	
	ALL STORY OF STREET	15. ELEVATIONS (SHOW DE KOS, AND WO)
	NOTICE OF INTENT TO: SUBSEQUENT REPORT OF:	GL 5'; KB 24'
	TEST WATER SHUT-OFF [
	FRACTURE TREAT	
	SHOOT OR ACIDIZE	
	PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone
	MULTIPLE COMPLETE	change on Form 9–330.).
	CHANGE ZONES	
	ABANDON•	
	(other) Subsequent Report of Running & Cementing 13	3/8" Casing
	17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	all certinent details, and give regiment dates
	including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen	rectionally doiled dive subsurface locations
		•
	Drilled a 17 1/2" hole to 295'. Ran 7 joints of 13	3/8", 72 lb, S-95 Buttress casing.
	as see . cemenced with 50 ppis of mater and)	[N] cacke of Downster
	14.9 ppg. Had good returns at 14.5 ppg. CIP at 11	:45 PM, 2/20/80. Nippled up 13 3/8"
	BOPE. Tested flange weld to 750 psi. OK. Tested pipe to 250 psi. OK. Drilling ahead with 12 1/4"	Hydril for closure on 3 1/2" drill
	the of the part of billing ahead with 12 1/4	Sit.
	Subsurface Safety Valve: Manu. and Type	Set @: Ft.
	18. I hereby certify that the foregoing is true and correct	
	SIGNED TEX Oreway TITLE Chief of Opera	LIONBITE Z8 February 80
Conforms		
pertinen	TITLE	GATE
provisio		
30 CFR 2	41.	

*See Instructions on Assemb Side

UNITED STATES	
DEPARTMENT OF THE INTERIOR	5. LEASE
	N/A
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A
CHAIRBY NOTICES AND DEDOCTE ON MICH.	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS	N/A
(Do not use this form for proposals to drift or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	
1. oit gas C	8. FARM OR LEASE NAME National Petroleum Reserve in Alaska
1. oit X g25 C ather	9. WELL NO.
2. NAME OF OPERATOR National Petroleum Reserve in	West Dease Test Well No. 1
Alaska (through Husky Oil NPR Operations, Inc.)	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	N/A
2525 C Street, Suite 400, Anchorage, AK 99503	11. SEC., T., R., M., OR BLK. AND SURVEY OF
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	AREA
below.)	Sec 21, T21N, R14W, UM
AT SURFACE: 2295' FEL; 2464' FNL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same	North Slope Alaska
AT TOTAL DEPTH: Same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DE, KDB, AND WO
NATAL AL INTER-	GL 5'; KB 24'
NOTICE OF INTENT TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330)
MULTIPLE COMPLETE GRANGE TONICS	·
CHANGE ZONES	
(other) Subsequent Report of Running & Cementing	3 5/8" Castna
	•
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen 	Cectionally dollar, dive substication leastings
Drilled 12 1/4" hole to 2980'. Logged with DLL/MSI	L/GR/CAL, BHCS/GR/TTI, CNL/FDC/
GR/Cal, HDT Dipmeter, and Sidewall Cores. Ran 70 Buttress casing. Ran centralizers as per program.	counts of 9 5/8", 53.5 1b, S-95
Cemented with 1600 sacks of Permafrost cement. Signal and sacks of Permafrost cement.	Snoe at 29/0'. FC at 2926'.
Had good returns. CIP at 5:30 AM, 3/5/80. Nipple	us some Tarted non 2000
UN. lested hydril to 1500 psi. Ok. Drilled FC 20	2026 and compare to 20/61
ed 9 5/8" casing to 1500 psi. OK. Drilled shoe at	· 2240 and coment to 294)'. Test-
Tested formation to a 0.62 psi/ft equivalent gradie	ont. OK Drilling about 4445 -
8 1/2" bit.	ox. Utilling anead with an
Subsurface Safety Valve: Manu. and Type	Set @: Ft.
18. I hereby certify that the foregoing is true and correct	
	. It march a
SIGNED THE Chief of Opera	ITIONBATE /7
With (This space for Federal or State orbit	:0 430)
t Para a Roman 2 Street Transport	TR . DATE 3-72-89
118 01	
21.	

*See Instructions on Reverse Side

18. Thereby certify that the foregoing is true and correct signed.	acionate 17 April 80
18. Thereby certify that the foregoing is true and correct	19 4 / -
Subsurface Safety Valve: Manu, and Type	Set @ I
The original Notice of Intent to Drill indicated the thicker geologic sequences, the objective TVD is Weber was notified on 3/21/80.	be proposed TVD to be $4,000^{\circ}$. Do sexpected to be 4500° . Mr. Jim
17. DESCRIBE PROPOSED OR COMPLETED OFFRATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent. The Official Notice of Intent to Drill indicated by	rectionally diffled, give subsurface locations a t to this work.)*
(other) Notice of Intent to Change Plans	THE PROPERTY ALASKA
CHANGE SONES	5 5 5 7 7 7 7 8 8 12 4
PULL OR ALTER CASING MULTIPLE COMPLETE	change on Form 9-230.)
SHOOT OR ACIDIZE \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	(NOTE: Report results of multiple completion or ac
TEST WATER SHUT-OFF	# 14
NOTICE OF INTENT TO: SUBSEQUENT REPORT OF:	GL 5'; KB 24'
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB. AND W
AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO.
AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same	12. COUNTY OR PARISH 13. STATE North Slope Alaska
belaw.)	Sec 21, T21N, RI4W, UM
2525 C Street, Suite 400, Anchorage, AK 99503 4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	II. SEC., T., R., M., OR BLK AND SURVEY (AREA
3. ADDRESS OF OPERATOR	N/A
 NAME OF OPERATOR National Petroleum Reserve in Alaska (through Husky Oil NPR Operations, Inc.) 	West Dease Test Well No. 1
well Well ather	9. WELL NO.
1 -2	8. FARM OR LEASE NAME National Petroleum Reserve in Alaska
(On not use this form for proposals to drill or to despen or plug back to a different respect, Use Form 9-311-C for such proposals.)	N/A
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A
DEPARTMENT OF THE INTERIOR	N/A

*Sex Instructions on Revenue Side

_. DATE __

pertinent

provisions of 30 CFR 221.

UNITED STATES		
DEPARTMENT OF THE INTERIOR	5. LEASE	
	N/A	_
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
COMPAN NOTIONS AND PERCENT ON THE CASE	N/A 7. UNIT AGREEMENT NAME	
SUNDRY NOTICES AND REPORTS ON WELLS	N/A	
(Do not use this form for proposals to drift or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME National	_
1. oil an gas	Petroleum Reserve in Alaska	
1. oil gas	9. WELL NO.	—
2. NAME OF OPERATOR National Petroleum Reserve in	West Dease Test Well No. 1	
Alaska (through Husky Oil NPR Operations, Inc.)	10. FIELD OR WILDCAT NAME	_
3. ADDRESS OF OPERATOR	N/A	
2525 C Street, Suite 400, Anchorage, AK 99503	11. SEC., T., R., M., OR BLK. AND SURVEY O	วล
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	AREA	
below.) AT SURFACE: 2295' FEL: 2464' FNL	Sec 21, T21N, R14W, UM	_
AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same	12. COUNTY OR PARISH 13. STATE North Slope Alaska	
AT TOTAL DEPTH: Same	North Slope Alaska -	_
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	14 AFINO.	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DE, KDB, AND W	_
	GL 5'; KB 24'	U)
NOTICE OF INTENT TO: SUBSEQUENT REPORT OF THE TEST WATER SHUT-OFF	30	_
TEST WATER SHUT-OFF	1 A 1-10\$	
SHOOT OR ACIDIZE		
REPAIR WELL	OMPTE: Report results of multiple domptenen or zo	
	34130.31	,,
MULTIPLE COMPLETE CHANGE ZONES CHANGE ZONES	Chapter Report results of multiple completion or zo Chapter Report results of multiple completion or zo Chapter Survey Chapter Report results of multiple completion or zo Chapter Report results of multiple completion or zo	
ABANDON* [] [U.S. Tage	GE, ALASKA	
(other) Notice of Intent to Abandon ANCHOR		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent	rectionally drilled, give subsurface incations a.	:s.
This is a confirming notice to abandon West Dease T	est Well No. 1 This well one	
drilled to 4170', logged, and tested. As a result	of the evaluation plans were	
developed to abandon this well. The abandonment pr	ocedure is attached.	
This plan has been discussed with and verbally appr	oved by Mr. Weber and Mr. Easson	ı
of the USGS Conservation Division.		
Subsurface Safety Valve; Manu. and Type	Sei @: s	t.
18. I hereby certify that the foragoing is true and correct		
SIGNED TITLE Chief of Opera	CIONBATE 18 April 80	
With (This space for Federal or State onto	e usel	=
DISTACではいる。	DATE	
ns of		-
21.		

*Sea Instructions on Reverse Seda

WEST DEASE TEST WELL NO. 1 ABANDONMENT PROCEDURE

- 1. Trip in with open ended drill pipe to 4050'.
- 2. Condition mud to uniform weight and viscosity for plugging.
- 3. Spot Plug No. 1, a 175 sack permafrost plug, mixed at 14.9 ppg. This is a +400' plug in the open hole, based on an average hole size of 9 1/4 inches. Spot a balanced plug with 21 barrels of water ahead and two barrels of water behind the cement.
- Pull up to 3400', lay down excess drill pipe. Circulate and condition for Plug No. 2.
- 5. Spot Plug No. 2, a 50 sack, permafrost plug, mixed at 14.9 ppg. This is a +100' plug in the open hole, based on an average hole size of 9 inches. Spot a balanced plug with 20 bbls water ahead and 2 bbls water behind cement.
- Pull up to 3070', lay down excess drill pipe. Circulate and condition for Plug No. 3.
- 7. Spot Plug No. 3, a 75 sack permafrost, mixed at 14.9 ppg. This is a +200' plug (100' in open hole (average hole size of 9 inches) and +100' in 9 5/8" casing). Spot a balanced plug with 19 bbls water ahead and 2 bbls water behind cement.
- 8. Pull up to \pm 2700' and slowly circulate mud, limit pressure.
- 9. Trip out and pick up a bit and 9 5/8", 53.5# scraper. RIH, clean out to ± 2850'. Trip out and pick up 9 5/8", 53.5# retainer. RIH and set retainer at ± 2820'. Condition mud.
- 10. Spot a 50 sack, permafrost plug on top of recainer, mixed at 14.9 ppg. This is 145' fill inside 9 5/8" casing. Spot a balanced plug with 17 bbls water shead and 2 bbls water behind cement.
- Pick up slowly out of the cement plug to 2700'. Slowly circulate mud. WOC 4 hours.
- 12. Reverse out mud with water. Reverse out water with diesel. The approximate capacity of the 9 5/8" from 2700' to surface is 191 bbls. Trip out, laying down drill pipe. DO NOT fill casing to surface. Leave ± 25' of 9 5/8" casing empty.
- 13. Nipple down BOP and wellhead to the 9 5/8" head.
- 14. Rig up the 4" line pipe, 9 5/8" head cover, and dry hole marker. Set the 4" line pipe ± 10' below the surface. Put a flared wireline entry guide on the bottom of the 4".

West Dease Test Well No. 1 Abandonment Procedure Page 2

15. Release rig and rig down for movement to Barrow No. 20. Clean location.

Information for well marker identification:

USGS - ONPRA West Dease Test Well No. 1 2295' FEL and 2464' FNL Sec 21, T21N, R14W, UM

H. M. Peterson

3. ADDRESS OF OPERATOR 2525 C Street, Suite 400, Anchorage, AX 99503 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA NOTICE OF INTENT TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF SHOOT OR ACIDIZE SHOOT OR ACIDI	
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS Sundant via this form for paraboshis to drill or to design or plug back to a ciliferant reservent, this form \$-311-C for such proposals.) Oil	5. LEASE
SUNDRY NOTICES AND REPORTS ON WELLS the notice this tarm for proposals to drill not despen or plug back to a cineman reservant. This report for such proposals.) 1. oil	N/A
Description	6. IF INDIAN, ALLOTTER OF TRIBE NAME N/A
1. oil well S well other 2. NAME OF OPERATOR National Petroleum Reserve in Alaska (through Husky Oil NPR Operations, Inc.) 3. ADDRESS OF OPERATOR 2. Street, Suite 400, Anchorage, AX 99503 4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17 below) AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA NOTICE OF INTENT TO: SUBSEQUENT REPORT OF: TEST WATER SMUT-OFF SHEAL BOX TO INDICATE NATURE OF NOTICE, REPART WATER SMUT-OFF CHANGE ZONES ABANDON' (other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dire measured and true vertical depths, for all markers and zones partinent from 3413' to 3313', was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of Petra from 3413' to 3313', was cement	7. UNIT AGREEMENT NAME
1. oil well S well other 2. NAME OF OPERATOR National Petroleum Reserve in Alaska (through Husky Oil NPR Operations, Inc.) 3. ADDRESS OF OPERATOR 2. Street, Suite 400, Anchorage, AX 99503 4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17 below) AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA NOTICE OF INTENT TO: SUBSEQUENT REPORT OF: TEST WATER SMUT-OFF SHEAL BOX TO INDICATE NATURE OF NOTICE, REPART WATER SMUT-OFF CHANGE ZONES ABANDON' (other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dire measured and true vertical depths, for all markers and zones partinent from 3413' to 3313', was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of Petra from 3413' to 3313', was cement	N/A
2. NAME OF OPERATOR National Petroleum Reserve in Alaska (through Husky Oil NPR Operations, Inc.) 3. ADDRESS OF OPERATOR 2525 C Street, Suite 400, Anchorage, AX 99503 4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17 below) AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA NOTICE OF INTENT TO: SUBSEQUENT REPORT OF: TEST WATER SAUT-OFF PROLICE REPAR WELL WHITE COMPLETE CHANGE COMPLETE CHANGE ZONES ABANDON' Content Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is die measured and true vertical depths for all markers and zones pertinent from 3413' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of Perma from 3413' to 3313', was cemented with 75 sacks of Perma from 3413' to 3313', was cemented with 75 sacks of Perma from 3413' to 3313', was cemented with 75 sacks of Perma from 3413' to 3313', was cemented with 75 sacks of Perma from 3413' to 3313', was cemented with 75 sacks of Perma from 3413' to 3313', was cemented with 75 sacks of Perma from 3413' to 3313', was cemented with 75 sacks of Perma from 3413' to 3640' was cemented with 75 sacks of Perma from 3413' to 3640' was cemented with 75 sacks of Perma from 3413' to 3640' was cemented with 75 sacks of Perma from 3413' to 3640' was cemented with 75 sacks of Perma from 3413' to 3640' was cemented with 75 sacks of Perma from 3413' to 3640' was cemented with 75 sacks of Perma from 3413' to 3640' was cemented with 75 sacks of Perma from 3413' to 3640' was cemented w	B. FARM CRILEASE NAME National
2. NAME OF OPERATOR National Petroleum Reserve in Alaska (through Husky Oil NPR Operations, Inc.) 3. ADDRESS OF OPERATOR 2525 C Street, Suite 400, Anchorage, AX 99503 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA NOTICE OF INTENT TO: SUBSEQUENT REPORT OF: TEST WATER SMUT-OFF	Petroleum Reserve in Alaska 9. WELL NO.
Alaska (through Husky Oil NPR Operations, Inc.) 3. ADDRESS OF OPERATOR 2525 C Street, Suite 400, Anchorage, AK 99503 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below) AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA NOTICE OF INTENT TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIOIZE BUILL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANOON' (other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dire measured and trive vertical depths for all markers and zones pertinent if this well was drilled to 4170', logged, and tested. logs and test, the well was abandoned as follows: 4038' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sack retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced m diesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. I haveby certify that the foregoing is true and correct SIGNED. TITLE Chief of Operative of the component of t	West Dease Test Well No. 1
3. ADDRESS OF OPERATOR 2525 C Street, Suite 400, Anchorage, AX 99503 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below) AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA NOTICE OF INTENT TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIOIZE REPAIR WELL REPORT OF SUBSEQUENT REPORT OF: TOTAL DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is die measured and true vertical depths for all markers and zones pertinent 10 and the vertical depths for all markers and zones pertinent 10 and the vertical depths for all markers and zones pertinent 10 and the vertical depths for all markers and zones pertinent 10 and the vertical depths for all markers and zones pertinent 10 and the vertical depths for all markers and zones pertinent 10 and 10 and the vertical depths for all markers and zones pertinent 10 and 10 a	10. FIELD OR WILDCAT NAME
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA NOTICE OF INTENT TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF SHOOT OF ACIDIZE REPAR WELL SHOOT OR ACIDIZE REPAR WELL SUBSEQUENT REPORT OF: TEST WATER CASING MULTIPLE COMPLETE COMPLETE COMPLETE COMPLETE COMPLETE CHANGE ZONES ABANDON* (other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is disa mreasured and two vertical depths for all markers and zones pertinent to the second dispers for all markers and zones pertinent from 3413' to 3313', was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 55 sack freatainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced m diesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Inscription of Operations of State office. TITLE Chief of Operations of State office.	N/A
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, CR OTHER DATA NOTICE OF INTENT TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	11. SEC., T., R., M OR BLK AND SURVEY OF
Delow.) AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA NOTICE OF INTENT TO: SUBSEQUENT PEPORT OF: TEST WATER SMUT-OFF FRACTURE TREAT SHOOT OR ACIOIZE REPAIR WELL REPAIR WELL REPORT OF: TEST WATER CASING MULLIPLE COMPLETE CHANGE ZONES ABANDON' (other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dire measured and trive vertical depths for all markers and zones pertinent to the starting and some section of the starting and zones pertinent was set at 211 and 211 and 212 and 212 and 213 and 214 and 214 and 215 acks of Perma from 3413' to 3313', was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sack retainer was set at 2816' and 50 sacks of Perma from the retainer. Top of cement at 2700'. Displaced medical Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Insception of State office. This space for Federal or State office.	AREA
AT SURFACE: 2295' FEL; 2464' FNL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA NOTICE OF INTENT TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	Sec 21, T21N, R14W, UM
AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA NOTICE OF INTENT TO: SUBSEQUENT REPORT OF: TEST WATER SMUT-OFF FRACT SHOOT OR ACIOIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dire measured and trive vertical dapths for all markers and zones pertinent in this well was drilled to 4170', logged, and tested. logs and test, the well was abandoned as follows: 4038' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sac retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced m diesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct signed. This space for Federal or Sizes office.	12. COUNTY OR PARISH 13. STATE
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA NOTICE OF INTENT TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	North Slope Alaska
NOTICE OF INTENT TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	14. API NO.
NOTICE OF INTENT TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL CR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state: including estimated date of starting any proposed work. If well is drive measured and true vertical depths for all markers and zones pertinent in the series of the starting and proposed work. If well is drive measured and true vertical depths for all markers and zones pertinent in the series of the retainer. Top of cement at 2700'. Displaced mediesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Theseby certify that the foregoing is true and correct SIGNED TITLE Chief of Operative Ch	
TEST WATER SMUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE PULL CR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is done measured and true vertical depths for all markers and zones pertinent to the starting and the proposed work. If well is done measured and true vertical depths for all markers and zones pertinent to the starting and the proposed work. If well is done measured and true vertical depths for all markers and zones pertinent to the starting and tested. Logs and test, the well was abandoned as follows: 4038' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of Plug, from 3069' to 2859', was cemented with 75 sack retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced mediesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Install dry hole marker. THUE Chief of Operations with	15. ELEVATIONS (SHOW DF. KDE, AND WO
TEST WATER SMUT-OFF FRACTURE TREAT SHOOT OR ACIOIZE SHOOT OR ACIOIZE PULL CR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ARANDON* (other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dire measured and true vertical depths for all markers and zones pertinent in this well was drilled to 4170', logged, and tested. logs and test, the well was abandoned as follows: 4038' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sac retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced m diesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu, and Type 18. Theseby certify that the foregoing is true and correct SIGNED TITLE Chief of Operative with the foregoing is true and correct. SIGNED TITLE Chief of Operative Chief of Opera	GL 5'; KB 24'
FRACTURE TREAT SHOOT OR ACIOIZE REPAIR WELL REPAIR WELL DULL CR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* Gother) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is done measured and trive vertical depths for all markers and zones pertinent in this well was drilled to 4170', logged, and tested. logs and test, the well was abandoned as follows: 4038' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sack retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced m diesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Theseby certify that the foregoing is true and correct SIGNED TITLE Chief of Operative with the foregoing is true and correct. TITLE Chief of Operative with the foregoing is true and correct.	
SHOOT OR ACIDIZE REPAIR WELL PULL CR ALTER CASING CHANGE ZONES ABANDON* (other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dire measured and true vertical depths for all markers and zones pertinent if this well was drilled to 4170', logged, and tested. logs and test, the well was abandoned as follows: 4038' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sack retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced m diesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Indicator certify that the foregoing is true and correct signed. Thus appace for Federal or State office.	
REPAIR WELL PULL CR ALTER CASING	
MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dire measured and true vertical depths for all markers and zones pertinent in this well was drilled to 4170', logged, and tested. logs and test, the well was abandoned as follows: 4038' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sac retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced m diesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Theseby certify that the foregoing is true and correct signed. Thus appace for Federal or State office.	NOTE: Report results of multiple completion or zon
CHANGE ZONES ABANDON* (other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dire measured and true vertical depths for all markers and zones pertinent if the sent of the well was abandoned as follows: 4038' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sack retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced midiesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Theseby certify that the foregoing is true and correct signed. Thus appace for federal or State office.	change on Form 9-330.)
(other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dire measured and true vertical depths for all markers and zones pertinent if this well was drilled to 4170', logged, and tested. logs and test, the well was abandoned as follows: 4038' to 3640' was demented with 175 sacks of Perma from 3413' to 3313', was demented with 50 sacks of plug, from 3069' to 2859', was demented with 75 sacks retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of dement at 2700'. Displaced middlesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correct signed. Thus Chief of Operative that the foregoing is true and correct signed.	
(other) Subsequent Report of Abandonment 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dire measured and true vertical depths for all markers and zones pertinent that the well was abandoned as follows: 4038' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sack retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced marker. Wellbore schematic attached. Subsurface Safety Valve: Manu, and Type 18. This chief of Operation of Company is true and correct signed. This space for Federal or State office.	
including estimated date of starting any proposed work. If well is dire measured and true vertical depths for all markers and zones pertinent. This well was drilled to 4170', logged, and tested. logs and test, the well was abandoned as follows: 4038' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sack retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced midiesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Theseby certify that the footgoing is true and correct signed. This space for Federal or State office.	
This well was drilled to 4170', logged, and tested. logs and test, the well was abandoned as follows: 4038' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sacks of retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced middlesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Instable certify that the foregoing is true and correct signed. This space for federal or State office.	all partinent details, and give partinent dates
logs and test, the well was abandoned as follows: 4038' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sack retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced m diesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED. THILE Chief of Operat With	to this work.)*
4038' to 3640' was cemented with 175 sacks of Perma from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sack retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced middlesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Instably certify that the foregoing is true and correct signed. This space for Federal or State office.	. Following an evaluation of the
from 3413' to 3313', was cemented with 50 sacks of plug, from 3069' to 2859', was cemented with 75 sack retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced modiesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Install dry hole marker. Thus Chief of Operative Chief of Operative Chief.	The first open hole plug from
plug, from 3069' to 2859', was cemented with 75 sac retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced m diesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Instably Certify that the foregoing is true and correct signed. This space for Federal or State office.	afrost cement. The second plug,
retainer was set at 2816' and 50 sacks of Permafros the retainer. Top of cement at 2700'. Displaced m diesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Install dry hole marker. This space for Federal or State office.	Permafrost cement. The third
the retainer. Top of cement at 2700'. Displaced m diesel. Nipple down BOP. Install dry hole marker. Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. Install dry hole marker. This space for Federal or State officer.	
Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. I hexeby certify that the foregoing is true and correct SIGNED TITLE Chief of Operat Wich (This space for Federal or State office	·
Wellbore schematic attached. Subsurface Safety Valve: Manu. and Type 18. I haveby certify that the footgoing is true and correct SIGNED TITLE Chief of Operat wich (This space for Federal or State office)	
Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foodgoing is true and correct SIGNED THIS Chief of Operat Wich (This space for Federal or State office)	Released rig 3/25/80 at 6:00 1
18. I hereby certify that the foregoing is true and correct SIGNED TITLE Chief of Operat wich (This space for Federal or State office	
18. I hereby certify that the foodgoing is true and correct SIGNED THILE Chief of Operat Wich (This space for Federal or State office)	
18. I hereby certify that the foodgoing is true and correct SIGNED THILE Chief of Operat Wich (This space for Federal or State office)	Set @j F
wich This space for Federal or State office	-
wich (Thus space for Federal or State office	7/ Ania c.
A T C II	ICIONSATE 21 April 80
	te use)
τ <u></u>	DATE
ns of # 21.	·

"See Instructions on Peress Side

DEDETATION OFFICE

7mm 1-216						OH	SHORE DIST. OFFICE
(Nov. 4-65)		UNITE	D STATES	នបខមរា វ វ	N DUPLICATE	Rust	m approved. get Bureau No. 42-R366 f.
	DEPAR	TMENT (OF THE IN	ITERIOR	i See ai he Aleustiana	r in-	1/4You 10 10 10 10 10 10
		GEOLOGIC	AL SURVE	Υ	rrvei e bi	1	
							RESIDENCE CIVISION
		OR RECC	MPLETION	REPORT A	AD LOG	N/A U.S.	NCHORAGE, ALASKA
is Type of we	LL: OII-	LE WEST	Day X	Other WII	doat	T. UNIT AGREEM	
A TYPE OF COL			_			N/A	
TALL	OVER DEN	KT. T STOR	Z PIFF.	Other	 	5 FARM OR LEA	National
2. NAME OF OPERA	Nation	al Petrol	eum Reserve	in Alaska			Reserve in AK
(through Hu		Operation	ns, Inc.)			9. WELL NO.	
3 MIDRERS OF DE	•					West Dease	e Test Well No
2525 C Stre	et, Suite 4	00, Ancho	rage, AK 9	9503			OOL, OR WILDCAT
	295' FEL; 2	-	OCEVICATE ENTA E	ny Gazie regoireme	n.,	N/A	I., ON BLOCK AND BURTET
						OR AREA	II, OH BLUCK ARE BEREE
At top prod. In	sterval reported be	· Low					
At lotal depth	5ame					Sec 21, T2	21N, R14W, UM
			14. FERMIT HO	DATI	:53010	12. COUNTY OR PARISE	13. STATE
			N/A	:	N/A		e Alaska
15. NATE SPIEDED	16. DATE TO. A	EACHED 17. DA	TE COMPL. (Ready .	to prod) 15. zu	CNATIONS IDE, RE	8, RT. GE. ETC.)* 15). ELEY. CASINGHEAD
2/19/80	9/23/8		N/A		'; Pad 7'		33"
20. TOTAL PEPTH. MD	A 198 21. PLU	G. SACK 7.D. M9	1 TVD 22, 07 913	LTIPER COMPL	20 INTERNAL	S ROTARY TOOLS	CARLE TOOLS
4170' TD		2700'	<u> </u>	N/A_		Al1	None
ZE, FRODUCING INTE	RYAL(S). OF THIS	COMPLETION—TO	P. SOTTOM, NAME (MO TAD TAD!			25. WAR DIRECTIONAL SCRYET MADE
22.7.1							
N/A 26 type F. Ferran	- FR						Yes
			110T Bd				
PDC/CNL/GIR	KYCAL, BHCS					ature Survey,	
Transc site	- weicht, in		ING RECURD REP	00FF 148 4 FF1 0 G # 42 F 11 F 8 12 E		nd Side <u>wall C</u> Na mereke	AMOUNT PULLED
20"	133 lb	· -,-· · <u>-</u>	ōi-, —	26" 17	5 Sy Parm	afrost Cmt	$-\frac{1}{N}\frac{N}{A}$
13/3/8"	72 1b		881			afrost Cmt	N/A
9 5/8"	53,51	h i 29	70			mafrost Cmt	- N/A
~	3.3.3.3			11.74	<u>ov un jei</u>	MATTOSE CINC	- <u>N/A</u>
29		LINER RECORI	,	•	30.	TUBING RECORD	
GIZE	тог (ма)	BOTTOM (MB)	SACKS CENENTS	SCRESK MD	5128	DEPTH SET (MD)	PACTER SET IND)
	i		.!				
1			<u> </u>	<u> </u>			7
31 полинаў порі во	Pusa (Interval, As	er dad number)		1		CTURE CEMENT SC	UEEZE. ETC.
				DEFTH INTEREA	는 (보D)	AMOUNT AND KIND OF	MATERIAL USED
				·	;;		
					_		
33.4		· · · · · · · · · · · · · · · · · · ·	Page				
33 * PART PERF PROPUCT	ION PRIDE	CTION METHOD (DUCTION	vor of ourse)		Producing as
SATE FIRST DEODUCT			Flowing, gas lift, p		ypr of pump)	akut-in)	
		CHON METHOD (pen Hole D	Flowing, pas lift, p ST PROD'S FOR		ypr of pump)		d & Abandoned
N/A PARE UF TEAT	HOLAR TEATED	pen Hole D	Flowing, pas 14ft, p ST	umping—aist and	1 48 MEZ	Plugge	
N/A		Pen Hole D	Flowing, pag teft, p ST FROD'N FOR TEST PERIOD	umping—aist and	TETM	Pluege	d & Abandoned
N/A NATE OF TEAT 3/10/80 FLOW TURNO PASSE. 318 psi	HOLAR TEATED 14 CANING PRESSUR	Pen Hole D	Floring, pas left, p ST FRUD'N FOR TEST FERIOD OU REC.	OIL - SEL.	TETM	Pluege	d & Abandoned
N/A DATE OF TEAT 3/12/80	HOLAR TEATED 14 CANING PRESSUR	Pen Hole D	Floring, pas left, p ST FRUD'N FOR TEST FERIOD OU REC.	OIL - SBL.	TETM	Pluege	d & Abandoned
N/A PATE OF TEAT 3/10/80 FEW TURNS PASS. 318 psi No Discostrion of a	HULAN TEATED 14 CANING PRESELV	Pen Hole D	Floring, pas left, p ST FRUD'N FOR TEST FERIOD OU REC.	OIL - SEL.	TETM	FINE OIL	d & Abandoned
N/A PATE UP TEAT 3/10/80 PLOW TURNE PASS. 318 psi As piagnosition or a Vented 33 12st or attach	HAVE AR TERTED 14 CANIFOR PRESSEN	Pen Hole D	Floring, pas left, p ST FRUD'N FOR TEST FERIOD OU REC.	OIL - SEL.	TETM	FINE OIL	d & Abandoned
N/A N/A N/A N/A N/A N/A N/A N/A	HOU AR TEATED 14 CANIDO PRESSUR AS ISOID, weed for MENTS	pen Hole D CHOKE NEE 1/4" E CACCULATED 24-HOLE RA; /net, rested, etc.	Flouring, gas left, p ST FRUD'N FOR TEST PERIOD OUL REC.	ort - sat.	TFTM WAY	A ST CTN E SEE	d & Abandoned
N/A N/A N/A N/A N/A N/A N/A N/A	HOU AR TEATED 14 CANIDO PRESSUR AS ISOID, weed for MENTS	pen Hole D CHOKE NEE 1/4" E CACCULATED 24-HOLE RA; /net, rested, etc.	Flowing, gas left, p ST PRINT'S POR TEST PERIOD OIL - REC.	ort - sat.	TFTM WAY	ANTI-A PLUESE A - HAL OIL A - HAL OIL TEST WITNESSED	d & Abandoned

*(See Instructions and Spaces for Additional Data on Reverse Side)

ADEX CITE

General: This form is designed for sadmitting a complete and correct well completion report and log on all types of fands and leases to either a Federal agency or a State agency, or both, parsuant to applicable Federal and/or State has and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from the local Federal and/or State editor. See instructions on items 22 and 21, and 33, below regarding separate reports for separate completions.

It not ther prior to the thire this shannary record is submitted, copies of all currently available logs (trillers, geologists, sample and core analysis, all types electric, etc.), formation and pressure tests, and directional surveys, should be utrached be extent required by applicable Federal and/or State laws and regulations. All attachments should be listed on this form, see from 35.

from 4: if there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Here 12: Indicate which elevation is used as reference (where not otherwise shown) for depth measurements given in other spaces on this form and in any attachments. Items 22 and 24: If this well is completed for separate production from more than one interval zone (multiple completion), so state in Here 22, and in item 24 show the producing interval, or intervals, (op(s), bottom(s) and name(s) (if any) for only the interval reported in Here 33. Submit a separate report (page) on this form, indequally identified, the producing th

for each additional interval to be separately produced, showing the additional data pertinent to such interval.

Hem 29: "Such Commit": Attached supplemental records for this well should show the details of any multiple stage concenting and the location of the ecocuting tool.

Hew 27: "Suchs Concurry Attached Supplemental recents for this were should show the returns of any material subsection of the supplemental for the supplemental form of the superfield produced. (See Instruction for Rems 22 and 24 above.)

31 SUMMARY OF PORC		эн. Сиотанте маккие				
LORDAL DAG	Tel:	Bu Litim	PROPERTY AND METULE PRESENTAL AND RESPECTED	MANIB	<u>*</u>	or
	i				MAIN DEPTH	TAUR TEAT. DEPTH
				Torok Sh	Surface	Straight Hole
SEE ATT	ACHED FOR SE	JMMARY OF C	RES AND DSTs	Gr/Pebble Sh	2919'	,,,,,,
				Kingak Sh	33701	
				U. Barrow Sd	3685'	
				L. Barrow Sd	38001	
				Sag River SS	3885'	
				Argillite	40201	
				[
į						

Well Completion Report National Petroleum Reserve in Alaska West Dease Test Well No. 1

SUMMARY OF CORES

CORE NO.	FORMATION	INTERVAL	CORE DESCRIPTION
1	Torok	600-630' (Rec 27')	Claystone: soft - gummy, with siltstone lamination. No indication of hydrocarbons.
2	Torok	1099-1129' (Rec 14')	Claystone: soft - gummy, micaceous, silty in part. No indication of hydrocarbons.
3	Torok	1900-1930' (Rec 30')	Shale: with lignitic inclusions, silty, grading to sandy siltstone. No indication of porosity or hydrocarbons.
4	"Pebble Shale"	2945-2975' (Rec 58')	Shale: very dark gray, silty, organic, abundant biotite, pyritic. No indication of hydrocarbons.
5	Upper Barrow sand	3700-3730' (Rec 30')	Sandstone: very fine - fine grained, silty and argillaceous, with siderite and galuconite, measured porosity 6-4%, fair oil show, calculated water saturation 100%. See DST No. 1 test results.
6	Upper Barrow sand	3730-3790' (Rec 58')	Sandstone: with interbedded Siltstone: clay filled, very poor porosity, nil permeability, generally poor oil show, calculated water saturation 100%.
7	Barrow sand	3790-3850' (Rec 60')	Predominantly <u>Siltstone</u> with interbedded sandstone and shale, very poor porosities in sandstone, with poor oil shows. Analysis indicates low permeability and high water saturation.
8	Sag River	3912-3973' (Rec 57')	Sandstone, Siltstone and Shale: sandstone exhibits very poor - nil porosity with generally poor spotty oil shows. Analysis indicates very low permeability and very high water saturation.
9	Sag River	3973-4033' (Rec 30')	Recovered core consisted of <u>Sandstone and Siltstone</u> with minor conglomerate, very poor porosity, nil - very poor permeability and very high water saturation.
10	Argillite	4150-4160° (Rec 1.5°)	Argillite: black with quartz veins and near vertical dip.


Well Completion Report National Petroleom Reserve in Alaska West_Dease Test Well No. 1

SUMMARY OF DRILL STEM TESTS

TEST NO.	FORMATION .	INTERVAL	TEST DESCRIPTION
1	Upper Barrow sand	3700-37301	Open Hole DST: Cushion 500' glycol, 1/4" surface choke. IHP: 2068 psi. 1st FP (29 min): Opened with immediate weak blow air continuing throughout period. 1st FP pressure: 277-298 psi; shut in well for 60 minutes; ISIP: 1374 psi.

2nd FP (237 min): Opened tool with weak blow increasing to fair blow, then decreasing to very weak blow in 2 hours-20 minutes, increasing slightly to weak blow in 3 hours, and continuing throughout remainder of test. No gas or fluid to surface. Second FP pressure: 324-375 psi; shut in well for 484 minutes; FSIP: 1602 psi; FHP: 2071 psi.

Recovered 0.69 bbls rat hole mud with small trace of oil.





Computed location based on data from Barr Automated Surveys, Inc. to Husky Oil NPR Operations, Inc. dated Aug. 11, 1979, a copy of which is on file with Tectonics, Inc., Anchorage, AK.

CERTIFICATE OF SURVEYOR

I hereby certify that I am properly registered and licensed to practice land surveying in the State of Alaska and that this plat represents a location survey made by me or under my supervision, and that all dimensions and other details are correct.

WEST DEASE 1-80

LAT. = 71° 09' 32.65" LONG. = 155° 37' 45.19"

Y = 6,276,319.45

X = 307, 294.09

ZONE 5





WEST DEASE TEST WELL No. 1

LOCATED IN

NE 1/4 PROTRACTED SEC.21, T2IN., R.14W, UMIAT MERIDIAN, AK.

SURVEYED FOR

HUSKY OIL


N. P. R. OPERATIONS, INC.




TECTONICS INC.


P.O. BOX 4-2295 , ANCHORAGE, AK 99509





PLAN VIEW





WEST DEASE DRILL PAD

OPERATIONS HISTORY

DATE AND FOOTAGE DRILLED AS OF 6:00 A.M.	ACTIVITY
2/18/80	Set 20" conductor at 101' and cemented with 175 sacks Permafrost cement. Welded conductor box; installed flow line. Picked up kelly.
2/19/80	Total Depth: 101'; Mud Weight: 8.6; Viscosity: 55. Completed rigging up. Spudded well February 19, 1980, at 6:00 a.m.
2/20/80 141'	TD: 242'; MW: 9.5; Vis: 57. Drilled to 190'; pulled out of hole. Installed three 14/32" jets. Ran in hole; drilled ahead.
2/21/80 53'	TD: 295'; MW: 9.7; Vis: 51. Drilled to 295'; circulated and surveyed. Made wiper trip; circulated. Pulled out of hole. Ran seven joints of 13-3/8", S-95, 72# casing to 288'. Cemented with 700 sacks Permafrost cement at 14.9 ppg; had returns at 14.5 ppg. Preceded cement with 20 barrels of water. Cement in place 2/20/80 at 11:45 p.m. Waited on cement.
2/22/80 0'	TD: 295'; MW: 9.2; Vis: 35. Waited on cement; mixed mud. Cut off 13-3/8" casing and welded on 13-3/8" head; tested head to 750 psi. Began nippling up blowout preventer.
2/23/80 305'	TD: 600'; MW: 9.5; Vis: 44. Finished nippling up blowout preventer. Ran in hole; tested Hydril to 250 psi. Drilled shoe and formation to 600'; circulated and surveyed. Pulled out of hole for core barrel. Picked up core barrel and ran in hole.
2/24/80 450'	TD: 1050'; MW: 9.6; Vis: 40. Cut Core No. 1, 600' to 630'. Pulled out of hole; received 27 feet of core. Ran in hole and reamed core hole. Drilled ahead.
2/25/80 350'	TD: 1400'; MW: 9.6; Vis: 40. Drilled to 1099'; pulled out of hole for core barrel. Cut Core No. 2, 1099' to 1129'. Pulled out of hole; recovered 14 feet of core. Ran in hole; reamed core hole. Drilled ahead.
2/26/80 457'	TD: 1857'; MW: 9.8; Vis: 43. Drilled to 1506'; surveyed. Drilled to 1571'; surveyed. Drilled ahead.

	·
2/27/80 158'	TD: 2015'; MW: 9.9; Vis: 42. Drilled to 1900'; surveyed. Pulled out of hole. Ran in hole with core barrel. Cut Core No. 3, 1900' to 1930'. Pulled out of hole; received 30 feet of core. Reamed core hole. Drilled to 2015'.
2/28/80 423'	TD: 2438'; MW: 10.2; Vis: 40. Drilled to 2351'; surveyed. Drilled ahead.
2/29/80 287	TD: 2725'; MW: 10.1; Vis: 40. Circulated while repairing gas detector. Drilled ahead.
3/1/80 201'	TD: 2926'; MW: 10.2; Vis: 43. Drilled to 2753'; circulated samples. Drilled to 2832'; circulated samples. Drilled to 2926'; surveyed. Pulled out of hole; tight four stands off bottom.
3/2/80 44' -	TD: 2970'; MW: 10.4; Vis: 54. Tripped for new bit. Washed and reamed from 2500' to 2926'. Conditioned mud. Drilled to 2945'; circulated samples. Pulled out of hole. Picked up core barrel and began coring.
3/3/80 10'	TD: 2980'; MW: 10.5; Vis: 55. Finished cutting Core No. 4, 2945' to 2975'. Pulled out of hole; laid down core and core barrel. Received 30 feet of core. Ran in hole and reamed core hole. Drilled to 2980'; conditioned hole. Pulled out of hole. Rigged up logging unit. Ran DLL/MSFL to 2450'; hit bridge. Ran in hole with bit; circulated and conditioned hole. Pulled out of hole for logs.
3/4/80 0'	TD: 2980'; MW: 10.5; Vis: 65. Rigged up logging unit; ran DLL/MSFL; BHCS/GR/TT1, FDC/CNL/GR/CAL, and HDT-Dipmeter. Began sidewall cores.

3/5/80

TD: 2980'; MW: 20.5; Vis: 57. Shot and o' recovered 16 sidewall cores. Ran in hole; circulated and conditioned hole for casing. Pulled out of hole; ran 70 joints of 9-5/8" casing; shoe at 2970'. Ran in hole; stabbed in and circulated. Mixed and pumped 1,600 sacks Permafrost cement. Cement in place 3/5/80 at 5:30 a.m. Waited on cement.

3/6/80 TD: 2980'; MW: 8.9; Vis: 33. Waited on cement; cleaned mud pits and mixed new mud. Prepared to land casing. Began cutting off 9-5/8" casing.

3/7/80 0' TD: 2980'; MW: 9.9; Vis: 34. Finished cutting 9-5/8" casing; welded on head and pressure tested to 1,000 psi. Set in and nippled up blowout preventer and tested. Installed wear bushing.

3/8/80 328'

TD: 3308'; MW: 10.1; Vis: 45. Strapped in with bottom hole assembly. Drilled float collar at 2926'; drilled cement to 2945'. Pressure tested 9-5/8" casing to 1,500 psi. Drilled shoe at 2970'; drilled formation to 2990'. Tested formation to a 0.62 psi equivalent. Drilled ahead.

3/9/80 181'

TD: 3489'; MW: 10.2; Vis: 50. Drilled to 3346'. Pulled out of hole; tight. Ran in hole; washed and reamed through bridges from 2980' to 3180'. Drilled ahead.

3/10/80 155'

TD: 3644'; MW: 10.2; Vis: 54. Drilled to 3582'; surveyed. Pulled out of hole. Ran in hole; reamed from 3522' to 3582'. Drilled ahead.

3/11/80 86'

TD: 3730'; MW: 10.2; Vis: 48. Drilled to 3700'. Circulated samples. Short tripped; circulated; surveyed. Pulled out of hole. Ran in hole with core barrel; cut Core No. 5, 3700' to 3732'. Pulled out of hole.

3/12/80 0'

TD: 3730'; MW: 10.2; Vis: 48. Laid down core and core barrel; recovered 30 feet of core. Ran in hole; reamed core hole. Circulated and conditioned mud. Waited on test tools. Pulled out of hole. Made up tools for Drill Stem Test No. 1; ran in hole. Ran 500-foot glycol cushion. Prepared to test surface lines.

3/13/80 0'

TD: 3730'; MW: 10.3; Vis: 45. Set packer at 3697'. Opened test tool at 7:10 a.m.; weak blow; closed at 7:40 a.m. Opened at 8:40 a.m.; weak blow; closed at 12:40 p.m. Dropped bar at 5:00 p.m. Circulated out test. Recovered 0.69 barrels rat hole fluid with less than 1% oil. Pulled packer at 8:40 p.m.; no fluid loss. Pulled out of hole to shoe; circulated. Pulled out of hole; laid down drill stem test tools. Pressures recorded during test at 3722' as follows: Initial hydrostatic pressure: 2,068 psi. First flow period BHFP: 277 to 298 psi. Initial shut-in pressure: 1,374 psi. Final flow period BHFP: 324 to 375 psi. Final shut-in pressure: 1,602 psi. Final hydrostatic pressure: 2,071 psi. Ran in hole with bottom hole assembly.

3/15/80 21	TD: 3790'; MW: 10.3; Vis: 44. Cut Core No. 6, 3732' to 3790'. Pulled 30 feet off bottom. Circulated and rotated; worked on No. 2 draw works engine.
3/16/80 0'	TD: 3790'; MW: 10.4; Vis: 45. Waited on weather for parts delivery. Received parts 3/15/80 at 11:00 p.m. Began repairing motor.
3/17/80 0'	TD: 3790'; MW: 10.4; Vis: 43. Completed repairs to draw works motor. Pulled out of hole; recovered 58 feet of core.
3/18/80 9' -	TD: 3799; MW: 10.3; Vis: 48. Tested blowout preventer equipment. Ran in hole; reamed core hole. Circulated and conditioned mud. Pulled out of hole. Ran in hole with core barrel and began coring.
3/19/80 113'	TD: 3912'; MW: 10.4; Vis: 45. Finished cutting Core No. 7, 3790' to 3850'. Pulled out of hole; recovered 60 feet of core. Ran in hole; reamed core hole. Drilled to 3912'; circulated samples.
3/20/80 60'	TD: 3972'; MW: 10.2; Vis: 50. Circulated; pulled out of hole. Picked up core barrel; ran in hole. Cut Core No. 8, 3912' to 3973'. Lost circulation. Mixed lost circulation material pill and pumped. Lost 150 barrels mud. Continued coring to 3973'. Pulled out of hole with 57 feet of core. Started in hole with core barrel.
3/21/80 98'	TD: 4070'; MW: 10.2; Vis: 42. Ran in hole with core barrel; cut Core No. 9, 3973' to 4033'. Pulled out of hole; recovered 30 feet of core. Made up bottom hole assembly; ran in hole and washed to bottom. Drilled ahead.
3/22/80 84'	TD: 4154'; MW: 10; Vis: 41. Drilled to 4150'; circulated samples. Pulled out of hole. Ran in hole with core barrel; cut Core No. 10, 4150' to 4160'.
3/23/80 16'	TD: 4170'; MW: 10.2; Vis: 51. Pulled out of hole with core; recovered 1.5 feet of core. Ran in hole; washed 10 feet to bottom. Circulated to log. Pulled out of hole, steel-line measured. Rigged up logging unit and ran in hole; hit bridge at 3375'. Pulled out of hole.

3/14/80 39' TD: 3769'; MW: 10.2; Vis: 42. Reamed 3670' to 3730'. Circulated and conditioned mud. Pulled out of hole; ran in hole with core barrel. Began coring.

3/24/80 0' TD: 4170'; MW: 10; Vis: 49. Conditioned hole. Ran Temperature Survey, GR/SP/CAL/DLL, GR/CAL/CNL/FDC, GR/BHC, CAL/MLL/ML, and HDT-Dipmeter. Began running Velocity Survey.

3/25/80 o' TD: 4170'; MW: 10; Vis: 51. Completed Velocity Survey. Shot 24 sidewall cores; recovered 24. Ran Temperature Survey. Pulled out of hole with logging unit. Ran in hole; circulated and conditioned mud. Pulled out of hole; laid down drill collars. Ran in hole with open-ended drill pipe to 4039'. Cement compressor broke down; waited on replacement.

3/26/80

TD: 4170'; PBTD: 2700'. Set Plug No. 1, 4038' to 3640', with 175 sacks Permafrost cement. Set Plug No. 2, 3413' to 3313', with 50 sacks Permafrost cement. Set Plug No. 3, 3069' to 2859', with 75 sacks Permafrost cement. Set 9-5/8" retainer at 2816'. Set Plug No. 4, 2816' to 2700', with 50 sacks Permafrost cement. Reversed out excess cement at 2700'. Cleaned pits. Reversed mud to water and water to diesel.

3/27/80

TD: 4170'; PBTD: 2700'. Laid down drill pipe; nippled down blowout preventer stack. Installed dry hole marker. Released rig March 26, 1980, at 6:00 p.m. Began rigging down.

DRILLING TIME ANALYSIS

WEST DEASE TEST WELL NO. 1

BRINKERHOFF SIGNAL, INC., RIG 31


Spud 2/19/80; Rig released 3/26/80

Total Depth: 4,170 Feet

	DR	LLI	NG	TH	ME .	ANA	LYS	15 (нои	RS)	- H	usk	Y N	PR C	PER	ATI	ONS	, IN	c		WE:	ST DE	EASE	TES	T WE	LL NO. 1	Page 2 of 4
	,		RIG UP/RIG DOWN	DRILLING	REAMING	TRIP	DEV. SURVEY	Σ	RIG REPAIR	CIRC. & COND. MUD		CASING & CEMENT		q d	dO	CHANGE BHA	LOST CIRC.	FISHING	CORING	DST	PLUG BACK	SQUEEZE CEMENT	~		THER	Operations at 6:00 a.m.	Comments
	2-28		2	2						2																Circulating	
	2-29		2	24						13																Drilling	
2 [3-1			44		144	l ₄			24									24							Tripping	
	3-2		\perp	4	314	63				2	24								7Կ					, .	14	Coring	Core No. 4: 2945' - 2975' Ran Schlumberger Wireline
	3-3		1			4 🖁				214	17	_			_											POH to Run Logs	Logs
	3-4	\perp			12	41 ₂			L	2	81 ⁵ .	71/2					_								l	Logging	
	3-5	_	_			2			· · · · · ·	2		115	18⅓				_					[Waiting on Cement	
-	3-6	╽		┙									5 ^յ ≨	15½	3	_	_					_				Nippling Up	
-	3-7	1_	1	3		3				Ļ					6	_	_						_		115	Testing Hydril	
	3-8	\perp	1	75		5	13																			Drilling	
	3-9	1.	1	9	1	$\mathfrak{J}^{1_{\underline{5}}}$	12									_										Drilling	
-	3-10	\perp	1	2 2		63	Ļ			3							_		1						l	Drilling	
_	3-11	\perp	\perp	\bot	1,5	74	ļ _ģ			915			,						32						21,5	POH with Core	Core No. 5: 3700' - 3732'
	3-12					2½				5-չ									_	16ե	\Box					Drill Stem Testing	DST No. 1
	3-13				훒	812			61 _á	2 3									3¹₂						2	Working on Hydromatic	

DRI	LLŧN	G T	IME	ANA	LYSI	IS (I	нои	RS)	- H	usk'	Y NE	PR C	PER	ATI	ONS	, IN	с.		MES	T DE	ASE	ŢĘS	T WE	LL NO. 1	Page3 of _4
ш + С	BIG DOWN	SNA	REAMING	⊤RIP	DEV. SURVEY		RIG REPAIR	CIRC. & COND. MUD	9kG	CASING & CEMENT		NIPPLE UP/DOWN BOP		CHANGE BHA	LOST CIRC.	FISHING	CORING	DST	PLUG BACK	SQUEEZE CEMENT	DIR. WORK	W O MAT./EQUIP.	ОТНЕК	Operations at 6:00 a.m.	Comments
3-14							12	J ₅									11 ¹ ₂							Coring	Core No. 6: 3732' - 3790'
3-15		╽.	<u> </u>				24									_								Working on Drawworks	
3-16			<u> </u>	ļ			24													_	_			Working on Drawworks	
3-17	<u> </u>	ļ		10 ¹ a	ų		3	31 ₃					3										4	Removing Core from Barr	el
3-18			ļ	7				1									14						2	Coring	Core No. 7: 3790' - 3850'
3-19		4		6				2									8						4	Circulating	Core No. 8: 3912' - 3973'
3-20	ļ		1/3	91/2													14			_				Going into Hole w/core Barnel	Core No. 9: 3973' - 4033'
3-21		205	1/2	2			,	1																Drilling	
<u>3-22</u>		34	11/2.	10				2	J _S						_	\Box	5կ						14	Coring	Core No. 10: 4150' - 4160'
3-23	<u> </u>	<u> </u>	12	4				2	175															Logging	Ran Schlumberger Wireline Logs
3-24	<u> </u>	\perp		9				3	12			_										-		Logging	
3-25]		_					24					Plugaina	Set Plugs 1, 2, 3, & 4
3-26	915	<u> </u>										6				_			. 6				2½	Laving Down Drill Pipe	Released Rig at 6:00 p.m.
3-27	24																							Riagina Down	,, <u>a</u> ,
3-28	24										- 1	- 1			İ									Rigging Down	

	DRIL	LIN	G ,ŤI	ME	ANA	LYS	IS (I	нои	RS)	- н	usk	Y NI	PR C	PER	ATI	ONS	, IN	с.		WEST	DEAS	SE_II	EST_	WELL	NO. 1	Page of
	DATE	RIG UP/RIG DOWN		REAMING	TRIP	DEV. SURVEY	Σ	RIG REPAIR	CIRC. & COND. MUD	٩C	CASING & CEMENT		NIPPLE UP/DOWN BOP	TEST BOP	CHANGE BHA	LOST CIRC.	FISHING	CORING	DST	PLUG BACK	SQUEEZE CEMENT	DIR. WORK	W O MAT./EQUIP.	ТНЕЯ	Operations at 6:00 a.m.	Comments
3-	29	24	<u> </u>		ļ																_				Rigging Down	
3-	30	24	ļ										_								_				Rigging Down	
3-	31	24															_				_				Rigging Down	Completed Rigging Down
L		<u> </u>	L_	1 2 3		لــا		أييا						l				لــِ				[
T0 HQ	IAI. URŞ	273' <u>í</u>	245 ¹ 5	114	152⅓	71 ₂	-0-	714	55½	58¼ 1	13	4715	33	2	-0-	-0-	-0-	8314	16 ¹ 5	30	-0-	-0-	-0-	402		
		Γ -	ī				i		- 1			_				7			- 1			~~_				
<u> </u>					r .				\dashv		_			-							_					
		ļ					_									_	_									
		<u> </u>														[_								
							l			ı	i		ŀ		ı			l			Ì	i				
									\Box	\neg						\Box	\neg									
													\dashv				一			\dashv	一	一				
		 -				\dashv	\dashv	 				寸		\dashv	1			\dashv	\dashv							
	-		 			— [+	\dashv	+				-	\dashv					\dashv				
_		ļ					-	\dashv						_	_	_	_				_			_		
		<u> </u>	1							ĺ													Į			



ARCTIC DRILLING SERVICES

COMPANT.	husk	y 0il	<u>NPR C</u>	<u>)perati</u>	<u>ion:</u>	s, lŋç,			\$1 A 1 E	£	Mas	ska		_						CASING PROGRAM:	20 Inch + 101 fr.
#fit	West	Deas	e Test	Well	Nφ.	<u>. l</u>			COURT	r	ort	h_4	Slope	<u>8</u> orougi	h						13-3/8 (nch o) 288 h.
CONTRACT	он В	rinke	rhof f	Signal	1,	Inc.			LOCAT	iON .	1	NPR/	1		SEG	_ 2	1	(WP	2 IN	ANG 14W	9-5/8 took at 2970 ft.
																				TOTAL	DEPTHh.
STUCK POII		-6-6-41	V187	OLIV		GELS		EI	THATIC	#4	,	0.16	(A [L AN	A1 Y515	DANE	Н	LTOR	: 1	CEC		
} <u>22 11</u>			Sac LEI	Pv		10	Serie D	and	+cTere	مادر		<u> </u>					0,0				
1980	1001	(b/gal		۰ <u>`</u> ۲۴	_	10 **** 10 ****	Meries D	¥ P1	,	Deal.	PF	M1	1-pm	ира т	ļ <u>.</u>					REMARKS	
[2719]	.120	0.0	1 2 1	l tu	64	14679	1 9 1	4 V.	l	-2	1 : : .	l	1000	1	1 <u>1 -</u>	2	<u>T.c.</u>	<u>98</u>	_=		
<u>3720</u> .	2 JQ.	2.5	52	15	32	18/24	8.5	28		4_	, <u>ļ</u>	. 3.	. 1350	180	177	_1.	Tr_	93			
2/21_	300			ed_P10	5 <u>.</u>						١	_	11.55	70000	ļ			ا ا		Waited on cem Mixed CaCl2	enc
$\frac{2/22}{2/22}$	288	9.2	35 44	_ <u>8</u>	1-54	-2/3-	77.7	J.Q.	!	1.	اد .	1.4	72000	42000 30000	L 4.	[2]	10	95	<u> </u>	Mixed Cacia	
$\frac{2/23}{2/24}$.	600	.9.3	44	10	1.9	6/11 5/8 4/9	6.0	14		2	עיי	ر) اد	30000	22000	1/2	극	-u	22	-	-	
$\frac{2/24}{2/25}$	1 <u>020</u> 1380 .	2.9	40 40	10.	1.3 Fa		2:2	וני או		4.	יי	3	35000	19600	1.1.4 Tr	151	'n	93			
2/26	1850	9.6 9.8	43		112	4/9	8.0	13		Ζ.	'n	3	41000	23000	tr	8	0	92			
2/27	2012	9.9	42	10	[13]	4/10	8.0	13		3	ō,	. 3	45000	25000	Ϋ́r	ا و ا	0	91			
2/28				11	14	4/10	8.0	14		4	ا . آ	. 3	38000	21000	1/4	li i 📗	0	89	_		
2/29	2725	10.1	40	10	Ī 3	4/11	8.0	9		3.	.0	, 3	35000	19600	1/4	1 <u>0</u>	Q.	9.0			
3/1		10.2		10	16	4/12	8.0	9		3	.0	٤.	41000	22900	Tr.	11	0_	88	<u>-</u> -		
3/2		10.4	.54	.10_	28	15/26	8.0	8		3_	.0	<u>. 3</u>	44000	24600	Tr_	12	0_	100		l	
3/3	2980	10.5	65	20	33	.4/12 15/26 22/31	.8.0	7.5		4 -	.0	٤.,	44000	22900 24600 24000 21000	<u>Tr</u>	12	0	, 88	=		
3/4	2980	10.5	<u>65</u>	. <u>20</u> .13		<u>22/31</u>	8.0	7.5.		4_	, <u>ο</u>	3	44000	21000 21000 23500 24500 61000 38000	Tr_	[12.]	0	88	<u> </u>		
3/5	<u>2980</u>	يميوا	57	13	28	13//5	8.0	8.5	ļ	3	<u>.0</u>	-3	42000	23500	174	12	ő	88	-=		
3/6	<u>2980</u> .	8.9		5 7		0/3 2/3 3/9	[발]	<u> 75</u>	l	- 1 ,	1.3	. 2	26500	24300	늣	-		.22.			
3/7	2980		34	/		4/.3			*** A	. <u>L</u>	۲-	<u>بخ</u> ا	108000	P1000	<u> }</u>	-2.	<u>u</u> .	24	· -		
3/8 . 3/9 .	3300 3485		- <u>45</u>	- 13	녆	3/9	0	2.2		- <u>i</u> -		1.9	08000	.30000	12.5	-6-		123			
	3640			14 15	150	6/12 6/18 6/12 6/10	9.3	6		_	1 <u>1</u> V.	2	62000	34700	177	8	ν.	35	-=		
3/4 <u>0</u> 3/41	17 10	10.2	48	14	12	6/12	10	<u>:</u>		<u>ء</u>	꾟	1 1	55000	30800	177	Z.	. ∺.	31			
3/12	1730	10.2	48	13	15	6/10	10	6.2		3	. 0	1 .	55000	30800	176	á	0	91	.	Running DST.	
3/12		10.3		.12	8	6/10 3/10 2/8 2/12	9.5	7		2	.0	.8	52000	29000	1/4	lio l	Tr	90	, ,	LANDITALIE EXT.	
3/14				11	3	2/8	10	8.4		2	3	. 9	5000	28000	1/4	10	Tr.	90			
1/15	3790	10.4		. 15	5	2/12	9.5	1.5		2	1	.8	45200	25312 24696 24640 22960	Tr	li i l	Τr	89			
3/16.	1790	10.5	43	1.5	3	2/10.	10	7., 8		2	.2	.8	44100	24696	Tr.	11	Tr.	.89	<u> </u>		
3/1/	.1790_	10.5	43	.11	.4	3/13	10	7 <u>. 5</u>		2	.2	. 9	44000	24640	TI.	Ш.	Tζ.	89			:
3/18		10.4		_18	7	4/18	10	<u>8</u>		<u>2</u> .	. 2	. 2	41000	22960	Tr.	ш	Tr_	.89			
3/19	3880	10.4		15	5	3/13 4/18 5/17 11/14	9.5	8	<u> </u>	2	1.12	.	<u> 48000</u>	26880	Tr.	Ш	[_	1 89	_		
3/20				20	15	11/14	_9	9.7		2_				.20160					=		
$\frac{1}{2}\frac{1/2}{2}\frac{1}{2}$.	4070.	16.2				3//-	<u> </u>	9.5	l					22900							
3/22	4152	$\frac{10}{10}$	41	9	11	3/7		9.8		3	┙.			22400							i
3/23	4170 4170	1 <u>0</u> 10	<u>51</u> 49	12 12	21 21	1 <u>2/20</u> 12/20	9 9	9.4		4	[.Ω	.]	43 <u>000</u>	24000 22400	1/4	5-	Tr.	91			
L7/ 4 1	4170	111	144	12	[Z.]	12/20	9	7.4	l. _	4 .	, <u>U</u>	زرا	40000	122400	11/4	<u> </u>	<u>Tr</u>	<u>.91</u>			

ARCTIC DRILLING SERVICES

COMPERT.	Hus) Wes	ky Oi L Dea	NPR se Tes	Opera st Wel	lion 1 No	ns, Inc		STATE COUNT	<i>l</i>	Nor	ka h	Slope	Boroug	h					CASING PROGRAM. 20 toch of 101 to 13-3/8 toch of 288 to	
CONTRACT	Br_ عن	inker	hoff 5	ignal	<u> I</u>	ne.			LOCAT	1014	NPI	RA			se	c _2	21	TWP	21N	RNG 14W 9-5/8 inch +1 2,970 in
STOCK POIN						T &	,		BARON											TOTAL DEPTH
balt.	DEPIN				Ţμ		μH		LIBATIO				HATE AN		SANI		LIO		CFC	1
1980		lb/gal	Sec API	. <u>"</u> "	<u></u>	10/ 10 m.n	Meter O	API	. —t	مريطون) والموطول	Pա	P1/41	C) () ()	La PHO:	•	, ,	3.	₩ *:	Mud, me/ml	REMARKS AND TREATMENT
. 3/.25	4170	10.0	.51.	.12	23	12/20	9.0	9.4		4	0.	. 3	139000	21800	174	9	Τг	91	_	Plugging.
3/26	2750		_ <u>46</u>	- <u>12</u>	1.3	. <u>6/15</u>	<u>11.0</u>	ָנֻטַּנְ	ļ	3	. 4	1.1	40000	22400	1/4	ĪΩ	Tr	90]=	Plugging
					!		i ;		l i							ļ	ļ	 —		
					-											i	<u> </u>	∮ —		
			' '	-	-					-		i					l .			
					-	1				-										
	'															ļ				
1									! ¨!		[]					l	i		 ·	
							_											l _		
											ļļ									
				·					,									L:	L	
												.				l,		!		
 																_				
					ΙI															
			- [·			_				İ	· —-					
1 .	İ				!															
\ - · · - · - ·		· j											ii					- 1	i	
1					-				i	.	- 	1							i	——————————————————————————————————————
1 1									·			-	· · • · · · ·			i		·-		
					` <u> </u>		·-··· }					-					-		·	- -
																-				
														· ···				·		
]	٠[_				_				
	f	·-															[
]				·			I			.].]						
	· .				[·			}			[_		_]]	
																		[]	
	— ·							i]			
·		· · ·			- -							\dashv	 -							
} ·				—·		·:	·	}			· - ~	-	——·	·——-						_ ·_ ·
						-	{		——-·f·			}		—·			· ·-	-		
I												-		 -}	<u>l</u>		-			
·					Т							1	↓		I	1			l	

PRINCE IN A SEA

											BI	T RE	COR	D			COUNTY						,	*1		
Bus.	έy Ο	11 NI	'R Ope	rations				inker	hoff Si	gnal,	Inc.						Nor	th :	Slo	pe .			gh	Alaska		
Nac	iona	1 Per	roleu	m Reserv		77	۱۱۱۱ ۱۱۱۱ مطاما		ase Test	11.71	Se C	21],	21 1	Nari		RANGE 14	ido n	h			BI OC	K		FIELD	
LLHI				in Alas				Ţι	ueici No	<u>. werr</u>	<u> </u>			41 1	ĠR	AW DBK 5	14	753							 	
- FUSUI									rani	MARF		3110	17	PÍ	+~`										NWDEN SURF	
DRALL									JOIN!	HIP	-00			LEHGTH		W1 R	WARE			MC		H #		SIRORE	INI DATE	
DRILLI									OHAR						M-O	1										
DRIGHT									ONALA COLLAN	NO	Đ Đ		ı b	I FRGTH		7	MARI			MI	DDEI			JAGREZ	T D DATE	
BIT ALC	911 5-70	Bil Mi(#	gall fact	SERIAL NO		12.5	/ <u>1</u>	14141		HIHUNS HUN	ACL HQQRS	IDHK	W 15.41 1000 1BS	MUTARY M & M	DEA AEMI	PUMP PRESS	POM No Line	IPS SPR	_	4v0 4vs		NULL B	1001		REMARKS FÜRMATIÖN C. FEIFID, 131	DATE
j	1 //2	HŢC	DSC3A	PR713	14	14	14	29	5 194	29.75	29,75	6,5	10	90		300	5½	151	9.	752	2	2	I			
2	124	HTC	QSC3A	AA870	11	11	[n]	_ 60	0 305	8.5	<u>38,25</u>	35.8	15	120	<i></i>	1300	5 ¹ 5	129	<u> 9.</u>	544		Ĺц	ı	1		
CH1	812	ACC	EH St	15689] <u>-</u> .		<u></u>	630	0 30	4	38.25	1.5	15	60		700	51,	61	9,	643	c	: þ	o p	<u> </u>		
RR2	124	HTC	DSC 3A	<u>AA8</u> 7Q	11	11	11	110	0. 500	12	50.25	41.6	25	100		1400	5 ¹ 2	12.	9.	744		2	1	ļ		
CH I	812	ACC	EH St	15689		<u> -</u>	<u> </u>	113	0 30	3.5	50.25	8.5	15	60		800	51 <u>5</u>	66	9.	844	عل	0	g o			
R82	124	HTC	0 <u>SC 3A</u>	AA870	11	11	11.	190	g. 800	23.75	89.Q	23.7	25-30	100		1500	5½	120	9.	844	4	6	1			
CHI	81/2	ACC	EH SE	15689		<u> </u>	ļ	1930	0 30	5,25	89.0	5.7	15	60		800	5½	60) 9 .	844	_ G	: þ (<u>a c</u>			
3	124	нтс	OSC 3A	KV657	11	11	11	2926	6 1026	67.5	156.5	15.2	30	100		1500	51/2	120	10	<u>' 43</u>	1 3	6	1			
. 4	124	STC	SDS	AK2634	11	11	11	2949	5 19	2,25	158,	8,4	30	100		1500	5½	120	10	54	4 2	1	μ	1		
СН1	81,	ACC.	EH St	15689	<u> -</u> _	<u> -</u> _	-	297	5 30	9.5	158 1 5.	3.15	20	80.		800	5½	60) [7	1 54	4 9	<u> </u>	<u>o</u> <u>to</u>			·
RR4	124,	STC	SDS	AK2634	11.	11	11	2980	0 5		159.5	6.6	30	100		1500	512	120	10	6:	5 2	h	I	ļ		
_5	81/2	нтс	X3A	WN836	11	11	Ιί	3346	6 366	22.25	18L 75	.16,4	30	85		1700	5½	11		50						_
6	81,	STC	spr	498NP	11	ΙĿ	11	3582	2 236	25	206 75	9.4	30	85		700	5 ¹ 2	11	0 2	<u>: 54</u>	4 6	6	1	:		
<u>.1</u> .	$\underline{8}_{2}^{1}$	нтс	xic .	WD396	11	11	11	3700	0 118	14.75	22.5	8	30	85		1700	515	11	010	48	3 5	5	I	:		
C <u>H 1</u>	81,	ACC	EH St	15689	_	-	-	3730	Q 3Q	4.75	22 <u>6</u> 25	6.3	15	60		800	535	6	0 2	41	<u> 3</u>	φ.	<u> </u>			
8	$8\frac{1}{2}$	Sec	\$44	898705	ijĨ	11	ΪΪ			CLE	AN OU	T RUN]	┷	\perp		\perp	↓	\perp	\perp			
С <u>н 1</u>	. <u>8½</u>	ACC	EH St	15689	7	ļ <u>-</u>	ļ- ļ	3790	0 60	15	241. 25	4	15	70		800	51/2	10	0[<u>3</u>	44	<u> </u>	φ.	2 <u>b</u> .			
cíií	8^{i_2}	ACC	EH St	15689	ļ. <u>.</u> .	<u> -</u> _	ĿJ	3850	0 60	14	25.125	4.2	15	70		800	51 <u>3</u>	10	010	44	4 G	φ.	o jo			
RR8	$8^{\underline{1}_{\underline{2}}}$	Sec	S44	898705	-	-		3912	2 62	4	25925	15.5	30	.75		1500	5½	12	0 0	44	<u> [3</u>	3	ļi	· L		
CIJ2	8^{1}_{2}	ACC	EH St	16799			-	3972	2 60	7.5	266. 75.	8	20	<u>60</u>		300	5½	9	0^{10}_{2}	44	1 0	ф.	<u> </u>			
CH2	8½	ACC	EH St	16799	_	<u>_</u>		4033	3 61	1 1	277 75	5.5	20	60		300	51 ₂	9	0 2 0 2	44	i G	φ,	<u> </u>			

Compliments of

LUMP	44)					h	ONTE	AT TON				В	IT RE	COF	O													
	Husl	ca DI	1 MPR	Operatio	ms,	40	<u>.</u>	Br 1	uke	chof f	Sign	alI	nc						BUNTY Amel	. e1						ATALE		
Nat	iona	il Pe	trole	ım Reserv	/e	ļ.	Mest Jest	o ∶Dea:	se 1	Test	Well	[&t.] [21			21 N		<u> </u>			- <u>- S</u> 1		2. <u>P</u> V.	'ro	ııot	<u>1</u> -	Alaa	Ka	
TU44	ĸ		iı	Alaska					PIPE		No.					01	ŁA W		14 1	lest	_				···-		 -	
UAT				-					10024		MAKI		Sité	i	*PF	W(3HK5		_				_				<u> </u>	
DRILL									MINI		. <u>Ni</u>						W(A							нР			ONDLE SUR!	
ORIGI									District CDI 4.5	4 H				۵ (I I NG [H		MP	M	AKE			₩0	ð{ i			PHONE	INI DATE	
MONN		<u> </u>							COLLA		NG NG	n p		10	(ENGTH	PU (0)		M.	AX!			MO	DIL			STRORE	I D DATE	
Bill Bill	8 (1 5)(t	BI) MFGR	Bil IYP(SERIAL NO OF BIT	I.	HISI T		ULES OU	114	HILL	HOWAS	ACC	C17HM	WINGHI	HUIARY	VERT	PDMP	Г	PUMA	' S		VD	Tot	יוו (100	-	ACMARKS	- -
	8 ¹ 2	†	 		 	 	<u> </u>	†	-		RUM	**************************************	 -	IQOO TBZ	B P M	OCA	PRESS	Mo	Lines	SPM	wi	Yıs	I	•	6		ORMATION TIC	DATI
		Sec	<u>\$44</u>	<u>898750</u>	<u> 111</u> .	lī Î	1.1	1	- 1		20.5	298. 25	5.7	35	70	Ļ.,	1500		5½	120	10	41	6	5	I			
CH2		1		16799	ļ. .	 =	ļ <i>=</i>	416	0	10	<u>5,25</u>	303.5	1.9	2Q	60	L.	1300	Ц	5½	80	įο	42	<u>G</u>	þο	Ь	i _	•	
9	<u>8½</u> .	HTC.	XDV.	H#1168	11.	11	11	417	0	10	3.25	306. 75	3	35	60		1500		51 <u>4</u>	20	10	50	ı	ı	1			
		ļ	·			ļ	ļ ,	ļ. _—			ļ								-					•	ľ			
		İ	i			<u>L</u> .	ļ										<u> </u>					\vdash			T			
		[.	ļ					<u> </u>														<u> </u>	 -	-	┢	 		
			ļ . <u>-</u>				L.		_]								L——	H		_		-	┢	H	┢	 		
[_	•	İi						\exists					. ——				-					├.		-	<u> </u>		<u> </u>
									7			·											-	_	-			
1			j ·	—.								\dashv									_		L.	_	L	·		
	ĺ	٠.				-	! - ∤	· · · -									. 4	\dashv		—ļ			Ц		۱			[
1	ı					- }	٠. ا			.		}		—	·					_					Ш			
	.			. :.	+				-			}	·					1										
f	}	.		.		.		· - ·	- +				·			[_ .]	. ,						-
	.	ł				-	}		į.									1				Ì					-	
+	إ	ļ	.	.	ļ	.]	.			[🛔		<u>.</u>		[Ī						T			
	į	ļ	-			_	.		┨.					. [Ī	i	T	i	- 1	1		_	一	\dashv			· +
- 1		-							_[.		[_		1		\neg	_	\dashv		\dashv	+			
	_ į.	[1						T						7		+	†	\dashv	_	一	\dashv	-	-+	 ·	· -	$ \vdash$ $-$
]				Ī				!		+			— : 	+		┪.	\dashv		\dashv	-	\dashv		\dashv	_ _ ·		—- —
]]	_		†	_		1	— I				+	···	-+	— † -	+	-+	—├	\dashv	\dashv	+	+	-			
			T			_	T.				+			 -		-+		+	\dashv	-	\dashv	-	\dashv	-	+		_	_ _
						—í_			Щ							- 1	- !	1		- 1	- 1	Ī	- [- 1	- 1			1

INTRODUCTION

After the 1976 drilling season, casing requirements were reviewed and design of casing strings standardized. Every effort was made to minimize weight and grade changes for simplicity, cost effectiveness, and to reduce chances of error during handling and running operations. Casing sizes were selected to accommodate designs for wells from 2,000' to 20,000'. Steel grade selection was the controlling factor on design with low hardness (Rockwell C24-28) steel being selected for Arctic application and possible H₂S environment. Below is listed casing sizes and design criteria required by Husky:

		YIELD S	TRENGTH		MUM PRES QUIREME (PSI)	
SIZE ⁽¹⁾	<u>WEIGHT</u>	MIN.	MAX.	COLLAPSE	BURST	CONNECTION
20"	133#/ft.	55,000	80,000	1,500	3,050	STC
13-3/8" (2)	72#/ft.	95,000	110,000	3,450	5,350	втс
9-5/8" (3)	53.5#/ft.	95,000	110,000	8,850	7,900	втс
9-3/4" ⁽³⁾ 7"	59.2#/ft. 38#/ft.	95,000 95,000	110,000 110,000	9,750 12,600	8,540 9,200	BTC BTC

⁽¹⁾ OD tolerance to be within API requirements unless adjustment absolutely necessary to meet ID requirements.

The following are additional requirements primarily to assure that the steel exhibits the metallurgical properties for Arctic applications and resistance to hydrogen embrittlement.

- 1. All pipe that is 13-3/8" OD and smaller to be quenched and tempered.
- 2. Run Charpy "V" notch tests on two random samples per 50 tons per heat. Minimum acceptance of 15 ft.-lb.@-50°F. Furnish test reports with order.
- 3. Perform all testing normally required for API approved pipe.
- 4. Furnish test reports for ladle analysis, quantitative analysis, and all check tests as per API requirements.

In addition, the following handling requirements were made:

- 1. Collars must be of same steel grade as pipe body.
- 2. Apply an API modified thread compound on mill-installed collar before bucking on.

Special drift to 12.25".

⁽³⁾ Special drift to 8.50".

- 3. Inspect at mill using Tuboscope's Amalog IV or equivalent on 9-3/4" and smaller, and at least magnetic particle on 13-3/8" and 20". All pipe to have special and area inspection together with full length API drifting. (Note special drifting requirements.)
- 4. Apply Arctic grade grease on all connections before installing thread protectors.
- 5. Install closed-end type thread protectors. Plastic plugs can be used to secure wrench openings in protectors.
- 6. Buck up thread protectors with impact wrench. Both mill and third party inspection personnel should observe the installation of thread protectors.
- 7. Palletize or containerize the tubulars, if possible, prior to shipment from mill. Do not haul pipe like cordwood in gondola railroad cars.
- 8. All pipe to be Range 3.
- 9. No "V" notching or metal stenciling on pipe body or collars.

Casing for West Dease Test Well No. 1 was programmed as follows: 20" conductor at ± 100 '; 13-3/8" deep conductor at ± 300 '; 9-5/8" casing at ± 2850 '. Actual casing run was 20" at 101'; 13-3/8" at 288'; and 9-5/8" at 2970'. The 9-5/8" annulus was left full of diesel from the top of Plug No. 4 at 2700' to the surface. This was to allow U. S. Geological Survey personnel to take temperature readings in the wellbore in the future.

CASING TALLY SUMMARY SHEET

FIELD National Petroleum Reserve in AK LEASE & WELL NO. West Desse Test Well No. 1 TALLY FOR 13 3/8 CASING

SUMM	ARY OF PAG	E MEASUREL	AENTS
	NO. OF JOINTS	FEET	.00'5
PAGE I	10	414	51
PAGE 2	! .		L
PAGE 3	 		
PAGE 4			
PAGE 5	<u> </u>		
PAGE 6			
PAGE ?	1.		
PAGE 8			
PAGE 9			
101AL	10	414	51

	SUMMARY OF DEPTH CALCULAT	IONS			
		NO. OF	FOOTAGE		
		JOINTS	FEET	2 00	
1	TOTAL CASING ON BACKS	10	414	51	
<u>2</u>	LESS CASING OUT LITS NOS.	3	121	95	
3	TOTAL (1 - 2)	<u> </u>	293	1	
4_	SHOE LENGTH		<i>£23</i>	56 54	
6	FLOAT LENGTH	-	2	7	
6	MISCELLANEOUS EQUIPMENT LENGTH			<u>00</u> _	
1_	TOTAL CASING AND EQUIPMENT FROM CEMENT HEAD (3 + 4 + 5 + 6)	- 	297	10	
8	LESS WELL DEPTH (KB REFERENCE)			┨ ┸ ┸.─	
9	"UP" ON LANDING JOINT	· [·]-	<u>-</u> -		

Weight indicator before comenting: _____; after slack-off: _____; inches slacked off

			,		506	MMARY OF STRING AS RUN			
EIGHT	GHADE	THREAD	MANUFACTURER	CONDITION NEW-USED		LOCATION IN STRING	NO OF JOINTS	FOOTAGE	INTERVAL
		 .	ļ		11 NO.	THRU NO.			· _
					ii wo	THRU NO.			·-
					ii NO	THRU NO.			
					JT NO.	THRU NO.			· _
	:				IT NO.	THRU NO.			*
—		— i		·	II NO.	THRU NO.			
	<u> </u>				IT NO.	THRU NO.			·

AGE	OF			CA	SING	TALLY		DATE:	<u>February</u>	<u> 19. 198</u>	\$O
IELD	NPRA		_ LEASE &	WELL NO	o. <u>W</u> .	est Dease No.	1	TALLY	FOR 13 3/	'8_" C#	\SI
THIOL		REMENT	CHECK MEAS	UREMENT	WT	TAIOL	FIRST MEASU	REMENT	CHECK MEAS	UREMENT	w
NO.	FEET	.001\$	FEET	.00%	GR.	NO.	FEET	.00°s	FEET	.00.5	G
- 1	42	68 (ncludine	Shoe)		1		ļ			1
2	42	.00		 -		2		<u> </u>	ļ		
3	40	. 26		ļ		3					
. 4	_40	87				4			1		
5	40	62	 			5				<u> </u>	
6	41	07				6		<u> </u>		<u> </u>	
7	42	02		<u> </u>		7		<u> </u>		<u> </u>	
в	42	22	<u> </u>			В				<u> </u>	
9	42	13]	9					
	40	64				0					L
TOTAL A	414	51				TOTAL D	•				
1						1					Γ
2						2				1	
3						3					
4]	4					
5					1	5					
6						6					1
7					1	7				1	1
8						8		1	1		
9						9				1	
0		<u> </u>				. 0		 	<u> </u>	1	†
TOTAL B				<u> </u>	i	TOTAL E				 	├
			1 .		,		•		<u> </u>		1
1		Ţ	1			TOTAL A		£ 1		Τ	}
2			 	 		TOTAL B	414	51		 	1
3		 		 		TOTAL C	···•			 	-
4		1	 	+		TOTAL D		_	 	1	į
5		 	 			TOTAL E		+	·	1	1
6		 	 	+		TOTAL		 			i
7		 	 -	+ -		PAGE	414	5 [!]
8		 	†-		, آ آ						
		 	 	 							
<u>9</u> j		:	 	 							
TOTAL C		†	!	! .							

CASING AND CEMENTING REPORT

WELL NAME West Dease Test Well No. 1
LOCATION National Petroleum Reserve in Alaska
RAN CASING AS FOLLOWS:
7 Jts 13 3/8" S-95 72#
Jts
Jts
Shoe @288'
Generalizer @ 278', 246', 205', and 164'.
FIRST STAGE
Sx of Cement 700 Type Pmfst Additives None 7 Excess 150
Preflush 20 Barrels Water Initial Pressure 0
Displacement 2.6 bbls. Final Pressure 0
Plug Down 11:45 PM
SECOND STACE - State Catt C
SECOND STAGE - Stage Collar @ N/A
Sx of Cement Type Additives % Excess
Preflush Initial Pressure
Displacement bbls. Final Pressure
Plug Down PM
Well Depth 295' Overall Casing Tally 289.52
KB to Top of Cut Off Casing Length of Landing Jt Removed
Weight Indicator Before Cementing lbs.
Weight Indicator After Slacking Offlbs.
Inches Slacked Off
Remarks:

CASING TALLY SUMMARY SHEET

FIELD National Petroleum Reserve in AK LEASE & WELL NO. West Dease Test Well No. 1 TALLY FOR 9.5/8 "CASING

SUMM	ABY OF PA	GE MEASURE	MENTS
	NO OF JOINTS	FEET	00.8
PAGE 1	50	2131	52
PAGE 2	20	836	69
PAGE 3	l :		
PAGE 4		! . 	
PAGE 5		· · - · · - · · · · · · · · · · · · · · ·	
PAGE 6			
PAGE 7			1
PAGE 8			_
PAGE 9			<u> </u>
TOTAL	70	2968	21

	SUMMARY OF DEPTH CALCULAT	IONS			
		NO. OF	FOOTAGE		
		DINTS	FEET	.001	
1_	TOTAL CASING ON RACKS	70	2968	21	
2.	LESS CASING OUT IJTS NOS.	. =		<u>. -</u>	
3	TOTAL (1 – 2)	70	2968	21	
4 .	SHOE LENGTH	_	11	75	
5	FLOAT LENGTH	_	2	_00	
6	MISCELLANEOUS EQUIPMENT LENGTH		=		
7	TOTAL CASING AND EQUIPMENT FROM CEMENT HEAD (3 + 4 + 5 + 6)	<u>,,, </u>	2971	96_	
В	LESS WELL DEPTH (KB REFERENCE)			_[
9	"UP" ON LANDING JOINT	1 1		1	

Weight indicator before cementing: _____; after stack-off: _____; inches stacked off _____.

DATE: December 29, 1980

					SU	MMARY OF STRING AS RUN			
V€ (G) (T	GRAD€	THREAD	MANUF ACTURED	TURED CONDITION NEW-USED		LOCATION IN STRING		FOOTAGE	INTERVAL
					31 NO.	THRU NO.			
				ļ	TI NO.	THRU NO.			
		!	<u> </u>		JENO.	THRU NO.			
1					JI NO.	THRU NO.		.	
					JI NO.	THRU NO.]]		
			ļ <u></u>		Jī NO.	THRU NO.			
		1	<u> </u>		JI NO.	TIINU NO			•

PAGE 1 OF 2 DATE: February 28, 1980 CASING TALLY NPRA LEASE & WELL NO. West Dease No. 1 TALLY FOR 9 5/8 " CASING FIELD_ FEET .00'S FEET .00'S GR. FEET .00'S FEET .00'S GR JOINT TAIQL NO. .25 و ا ا ہ TOTAL A TOTAL D 7.7 TOTAL B TOTAL E TOTAL A TOTAL B TOTAL C TOTAL D TOTAL E TOTAL

TOTAL C

PAGE


DATE: February 28, 1980 LEASE & WELL NO. West Dease No. 1 TALLY FOR 9 5/8 " CASING FIELD NPRA JOINT FIRST MEASUREMENT ICHECK MEASUREMENT WT FIRST MEASUREMENT CHECK MEASUREMENT WT TAIOL FEET | 00'S | FEET | 00'S GR NQ. DO'S | FEET | DO'S GR. NO. FEET .52 TOTAL A TOTAL D <u>8</u>2 B JATOT TOTAL E 00 (Shoe) TOTAL A 75 (Float Collar) TOTAL B TOTAL C TOTAL D TOTAL E TOTAL PAGE 0 | TOTAL C 75 !


CASING TALLY

PAGE __2 OF _2

CASING AND CEMENTING REPORT

WELL NAME West Dease Test Well No. 1	
LOCATION National Petroleum Reserve in Alaska	
RAN CASING AS FOLLOWS:	
70 Jts 9 5/8" 53.5 Buttress 5-95 Range	3
Jts	_
Jts	
Shoe @2970' Float @2926' DV @	
Centralizer @ 2960', 2882', 2798', 2715', 2633', 2545', I28', 86', 43'	
FIRST STAGE	
Sx of Cement 1600 Type Pmfst Additives Z Excess	
Preflush None Initial Pressure 0	
Displacement 19.3 bbls. Final Pressure 400	
Plug Down 5:30 PM	
SECOND STAGE - Stage Collar @	
Sx of Cement Type Additives Z Excess	
Preflush Initial Pressure	
Displacement bbls. Final Pressure	
Plug Down PM	
Well Depth 2980' Overall Casing Tally 2971.96	
KB to Top of Cut Off Casing Length of Landing Jt Removed	_
Weight Indicator Before Cementing lbs.	
Weight Indicator After Slacking Off lbs.	
inches Slacked Off	
lemarks:	





RIG INVENTORY

Draw Works

National T-20, single drum grooved for 1" wireline with 15" double hydromatic brake, automatic breakout and make up catheads, driven by one set GMC diesel twin 671 engines, 300 HP, through Allison torque converter, all mounted on single skid. One Westinghouse 3YC air compressor driven by main PTO.

Mast

Lee C. Moore, 95' high with 9-foot wide front by spread cantilever. Gross nominal capacity 290,000 lbs. with racking board capacity of 130 stands 4-1/2" drill pipe (doubles). Mast crown block capable of stringing eight 1" wire lines.

Subbase

Three box sections, two at ground level 8 feet high, 9 feet wide, 37 feet long; center section 8 feet 5 inches high, 9 feet wide and 37 feet long. Clear working space from bottom of rotary beam to bottom of subbase is 14 feet 7 inches. Rotary table to bottom of subbase is 17 feet (add four inches for rig matts).

Rig Matts

Ten 4" x 16' long x 8' wide; fifteen 4" x 24' long x 8' wide.

Traveling Blocks

IDECO, 160 ton, four 1" sheave combination block and hook.

Swivel

EMSCO L-140, 6-5/8" left-hand API regular pin, 140 ton capacity.

Bails

Byron Jackson, 2-1/4" x 108", links 250 ton capacity.

Rotary Table

Oilwell 17-1/2" split square drive master bushing, 275 ton static load capacity.

Mud Tank

Three-section insulated tank. Capacity shale tank: 75 barrels; capacity middle tank: 100 barrels; capacity suction tank: 112 barrels. Shale tank equipped with shale jet and 16-barrel trip tank. Total capacity: 303 barrels.

Shaker

Single Brandt tandem separator driven by 3 HP, three-phase, 440 volt, 1,750 RPM explosion-proof electric motor.

Degasser

Drilco, see-flo, driven by 7-1/2 HP, three-phase, 440 volt, explosion-proof motor with 1/2 HP, three-phase, 440 volt explosion-proof blower.

Desander

Pioneer Model S2-12; capacity: 500 GPM.

Desilter

Pioneer Model T8-6; capacity: 500 GPM.

Mud Mixer

One Dreco, driven by 5 HP, three-phase, 440 volt, 1,725 RPM explosion-proof motor.

Hopper

One low pressure mud-mixing hopper.

Generators

One Caterpillar Model 3406, 210 KW; one Caterpillar, skid-mounted in Hercable house, 8' 5'' high x 8' 2'' wide x 29' 5'' long; one Caterpillar Model D-333, 100 KW standby.

Boilers

Two Continental, 40 HP, 120 psi diesel-fired, skid-mounted, in Hercable house, 8' 4" high x 8' wide x 35' long.

Steam Heaters

Seven Model 90H Trane steam heaters; three Model 96H Trane steam heaters.

Tongs

Byron Jackson, Type "C", short lever, with heads.

Indicator

(Weight) Cameron, Type "C", up to 400,000 lbs.

Indicator

(Rotary Torque) Martin Decker hydraulic piston wheel type with remote gauge at driller's position.

Indicator

(Tong Torque) Martin Decker, hydraulic piston type with remote gauge.

Mud Box

OKE mud box with 3-1/2" and 4-1/2" rubbers.

Slips

One set for 3-1/2" drill pipe. One set for 4-1/2" drill pipe.

Elevators

One set for 3-1/2" drill pipe, 18 degrees taper. One set for 4-1/2" drill pipe, 18 degrees taper.

<u>Kelly</u>

One square 4-1/4" drive, 4" FH pin, 6-5/8" API regular left-hand box. One square, 3-1/2" drive, 3-1/2" IF pin, 6-5/8" API regular left-hand box.

Kelly Bushing

VARCO, square drive, 3-1/2" rollers.

Pumps

(Drilling and Cementing) Two Halliburton, HT-400D, single acting piston pumps with Gist Oil Tool API fluid ends, each driven by GMC diesel 8V-71N, 300 HP engines through an Allis-Chalmers torque converter, Model 8FW1801-1, and a twin-disc power shift transmission, Model No. T-A-51-2003. Continuous duty with 5-1/2" API piston at maximum of 75 SPM will produce 185 GPM for each pump with maximum pressure up to 3,000 psi. Both pumps can be run simultaneously if desired. The discharge mud line furnished by contractor from pumps to swivel connection is designed for 3,000 psi working pressure. Each pump unit mounted on 8' 4" high x 10' wide x 40' long covered skid.

Air Compressors

One LeRoi 34C mounted on draw works compound. One Ingersoll Rand Model 71-T2-T3011 TM, driven by 10 HP, 440 volt, 1725 RPM explosion-proof electric motor.



Water Tanks

One 7' high x 9' wide x 20' long, insulated water tank, mounted in the subbase; capacity: 225 barrels. One 17' 4" long x 6' 4" wide; capacity: 120 barrels.

Fuel Tanks

One 20' long x 8' 6" wide; capacity: 6,000 gallons.

Blowout Preventer Equipment

One 10" 900 dual Shaffer gate LWS with 3" flanged side outlet one side.

One 10" 900 GK Hydril.

One 10" 900 drill spool with 2" flanged outlets both sides.

One set 4-1/2" pipe rams. One set 3-1/2" pipe rams.

One set blind rams.

One upper kelly cock TIW 6-5/8" regular LH box to pin.

Two TIW 10,000 psi lower kelly cocks, 4-1/2" XH joints.

Two TIW 10,000 psi lower kelly cocks, 3-1/2" IF joints.

One inside preventer, 10,000 lb. Hydril, 4-1/2" XH.

One inside preventer, 10,000 lb. Hydril, 3-1/2" IF.

Choke Manifold

Three-inch, 3,000 lb., with one 2" OCT adjustable choke; one 2" OCT positive choke and space for automatic choke.

Closing Unit

One 80-gallon Hydril closing unit with four nitrogen bottle backup. Four-station Koomey control manifold with four-station air operated remote stations.

Drill Pipe

5,000 feet, 4-1/2", 16.6 lb., Grade E, 4-1/2" XH joints; 5,000 feet, 3-1/2", 15.5 lb., Grade E, 3-1/2" IF joints.

Drill Collars

Nineteen 6-1/4" x 2-1/4" x 30' four-inch H90 tool joints.

One 6-1/4" x 2-1/4" x 30' four-inch H90 x 4-1/2" regular bottom collar.

Nineteen 4-3/4" x 1-3/4" x 30' x 3-1/2" IF x 3-1/2" regular bottom

One 4-3/4" x 1-3/4" x 30' x 3-1/2" IF x 3-1/2" regular bottom collar.

Subs

Two 4-1/2" XH kelly savor subs.
Two 3-1/2" IF kelly savor subs.
Two 4-1/2" XH box to 4" H90 pin (DC crossover).
Two 4" H90 box to 4-1/2" regular box (bit sub).
Two 3-1/2" IF box to 2-7/8" API regular box (bit sub).

Forklift

One 966 Caterpillar, equipped with 60-inch forks.

Pipe Racks

One V door ramp with stairs. One tail-walk section, 6' 1" wide x 43" high x 42 feet long. Four pipe-rack sections, 43" high x 4' wide x 28 feet long.

